

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological and Heritage Sites / Monuments**

Serial No.: RJ/NGR-290 **SECTION I: IDENTIFICATION** 1. Name Present Kund **Past** Other Name (if any): 2. Location / LONGITUDE 75°15'E **LATITUDE** 27°40'N Address Malkot Fort Metra city Village (village code) Post: Merta city **District**: Nagaur **PIN:** 341510 State: Rajasthan Approach The Kund is situated at Malkot in Merta city. It is 80km away from Nagaur. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Others (specify) Kund Govt. building Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a water reservour. No structures water remains today. Instead has grown Vegetation on the ground. It Public square Bridge is relatively not very deep. The Tunnel Park or garden kund served as a source of water

for the usage in the fort. It is a

square concrete Kund.

Gravevard

Tank Cave

Baolis, Well

Other engineering structure

4. Property Use

**ABANDONED** √/ IN USE

Present : Kund Past : Kund

5. Age (Source)

PERIOD : 17<sup>th</sup>Century AD

YEARS

Precise date of Construction

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

**Public**: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)

Private :

Any other (Please specify) : Name :

Address : Phone :

7. Association

• WITH EVENTS

√ In History : In Rituals : In Building Construction :

In Building Construction : Any other (specify)

WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance				
√ 	Architectural Archaeological Historical Religious Any other (specify)	:		
	<u>;</u>	SEC	CTION II: DESCRIPTION	
9.	<b>Physical Description and De</b>	cora	ative Features	
•	Context Urban√ / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)	
	Carroananigo		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	<b>Quantification</b> Area Dimension ( L x B x H)	:		
	Number of Blocks Number of Storys	:	01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The Kund is oriented East/West and Faces the West.	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	: : : : : : : : : : : : : : : : : : : :	No ornamentation	
10	. Construction Technology			
	Structural System Building Techniques	:	Five walls made of brick and motor.	
	Material of Construction	:	Brick, cement/motar	

11. Condition Assessment				
In General	Good /√ Fair			
	Sign of Deterioration Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sheet if necessary):				
12. Threats to the Property				
	<ul><li>√ Natural</li><li>Negligence</li><li>Vandalism</li><li>Urban Pressures</li></ul>			

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS