



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-295

SECTION I : IDENTIFICATION

1. Name

Present : Well
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 40' N

Address

Near Malkot Fort, Merta City.

: Village (village code)

Post: Merta City

District: Nagaur

State: Rajasthan

PIN: 341510

Approach

: The Well is situated near Malkot Fort, Merta. It is 80km from Bus stand, Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify) |
| | Well |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |

Note: It is situated on a deserted area and is no more in use. The well still has water but is filled with filth and garbage.

<input type="checkbox"/>	Tank
<input type="checkbox"/>	Cave

4. Property Use

ABANDONED / IN USE

Present :
Past :

5. Age (Source)

PERIOD : 17th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
 India / State Archaeology
 Department / Any Other (Please
 specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

☒ Architectural

English Bond Method

<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

- **Context**

Urban / Rural Setting

Surroundings

*** Drawings** (Attach extra sheet if necessary)

Urban Setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) : _____ (m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys : 01

- **Spatial Organization**

Orientation : The Well is oriented North/South and faces the North

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors : A square raised platform, used for bathing/cleaning utensils purpose

Interiors : Brick encasing

Movable Collections :

Any Other (specify) :

10. Construction Technology

- | | | |
|---------------------------------|---|---------------------------|
| Structural System | : | English Bond Method |
| Building Techniques | : | Trabeate system |
| Material of Construction | : | Bricks stone and plaster. |

11. Condition Assessment

In General **Good / Fair**

☐ Sign of Deterioration

<input checked="" type="checkbox"/>	Serious Deterioration
<input type="checkbox"/>	Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Very Poor

12. Threats to the Property

<input checked="" type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Not available

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS