



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-308

SECTION I: IDENTIFICATION

1. Name

Present : Shiv Mandir
Past :
Other Name (if any):

2. Location /

LONGITUDE 75°15'E

LATITUDE 27°40'N

Address

Ram Sita Mandir, Sewak Chowk, Ladanu

: Village (village code)

Post: Ladanu

District: Nagaur

State: Rajasthan

PIN: 341306

Approach

: The Temple is situated near Sewak Chowk at Ladanu in Nagaur District. It is 90km away from Nagaur bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: This is a temple dedicated to Lord Shiva. It is an old but renovated structure. It has an open porch which is followed by a gateway at the entrance. The shrine of Shiva with Nandi housed in the sanctum. It has a showcase

which consists other subordinate

4. Property Use

ABANDONED √ / IN USE

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 18th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - √ **In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input type="checkbox"/>	Architectural	.
<input type="checkbox"/>	Archaeological	.
<input type="checkbox"/>	Historical	.
<input checked="" type="checkbox"/>	Religious	.
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- Context** * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting
Surroundings
Stand in Isolation
Integral part of a Landscape / Street / Complex
- Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01
- Spatial Organization**
Orientation : The Temple is oriented North/South and faces the South.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- Ornamentation**
Exteriors : A very ordinary structure and not much decorated.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone, brick, rubble masonry

11. Condition Assessment

In General

Good✓ / Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

The temple holds a good condition.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Gupta Dr.Mohan Lal, Udaipur Sambhag Ka Jilevar Sanskritik aur eatihasik adhayayan, Rajasthani Granthagar,Jodhpur, 2007-2009

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS