



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-312

SECTION I: IDENTIFICATION

1. Name

Present : Chhatri
Past :
Other Name (if any):

2. Location /

LONGITUDE 75°15'E

LATITUDE 27°40'N

Address

Kundal Talab Ka Pal, Merta City

: Village (village code)

Post: Merta City

District: Nagaur

State: Rajasthan

PIN: 341510

Approach

: The Chhatri is situated at Kundal Talab Pal at Merta city in Nagaur district. It is a 80km away from Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|--------------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify) Chhatri |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: The Chhatri is in a very bad state. It is surrounded by thick Vegetation and dried lands. It is situated at a height. Only one face of Chhatri is left. Small parts of turrets can be seen, but no central dome.

4. Property Use

ABANDONED √ / IN USE

Present : Memorial
Past : Memorial

5. Age (Source)

PERIOD : 17th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - √ **In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

<input type="checkbox"/>	Architectural
<input type="checkbox"/>	Archaeological
<input checked="" type="checkbox"/>	Historical
<input type="checkbox"/>	Religious
<input type="checkbox"/>	Any other (specify) _____ :

9. Physical Description and Decorative Features

- ## ARCHITECTURAL STYLE

- | | |
|----------------------------|--|
| • Ornamentation | |
| Exteriors | : The cusped arches are very beautifully chiseled. The spandrel is composed of beautiful relief's. The base of the pillars in loaded with ornamentation. |
| Interiors | : |
| Movable Collections | : |
| Any Other (specify) | : |

Structural System : Indo-Persian
Building Techniques : Arcuate system
Material of Construction : Stone, bricks, marble , rubble masonry.

11. Condition Assessment

In General

Good / ☒ Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

. Dilapidated

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS