

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-322 **SECTION I: IDENTIFICATION** 1. Name Present Gateway (Meera Mahal) **Past** Other Name (if any): 2. Location / LONGITUDE 75°15'E LATITUDE 27°40'N Address Meera Mahal, Near Vishnu Sarobar, Merta Village (village code) Post: Merta city **District**: Nagaur State: Rajasthan **PIN:** 341510 Approach The Gate is situated Meera Mahal at Merta in Nagaur District. It is 80km away from Nagaur. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related **Note:** The Gateway is in a ruined structures state. It has pointed arch opening. Public square Bridge Tunnel Park or garden Other engineering structure Gravevard Baolis, Well Tank Cave

4. Property Use

ABANDONED ∜ IN USE

:

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 16th Century AD

YEARS :

Precise date of Construction : Completion :

Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)

Private :

Any other (Please specify)

Name : Address :

Phone :

7. Association

• WITH EVENTS

In History

In Rituals :

In Building Construction

Any other (specify)

WITH PERSONS

Patron :

Architect / Engineer :

Any other (specify) :

8.	Statement of Significance			
$\sqrt{}$	Architectural	. Pointed arch opening.		
	Archaeological Historical			
	Religious			
	Any other (specify)	:		
	:	SECTION II: DESCRIPTION		
9. Physical Description and Decorative Features				
•	Context Urban√ / Rural Setting	* Drawings (Attach extra sheet if necessary)		
	Surroundings	Ctand in laciation		
		Stand in Isolation Integral part of a Landscape / Street / Complex		
		integral part of a Landocape / Otroot / Complex		
•	Quantification			
	Area Dimension (LxBxH)	: (m / cm/ feet / inch)		
	Number of Blocks	(III / CIII/ leet / IIICII)		
	Number of Storys	:		
_	Spatial Organization			
•	Spatial Organization Orientation	: The Gate is oriented North/South and faces the North.		
	Plan	:		
	Allocation of Spaces	:		
ΑF	RCHITECTURAL STYLE			
•	Ornamentation			
	Exteriors	:		
	Interiors	:		
۸۰	Movable Collections ny Other (specify)	: :		
AI	iy Other (specify)	•		
10	. Construction Technology			
	Structural System	: Indo-Islamic		
	Building Techniques Material of Construction	: Arcuate system: Stone and plaster.		
	waterial of construction	. Storie and plaster.		

11. Condition Assessment				
In General	Good /√ Fair			
	Sign of Deterioration Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sh	neet if necessary):			
Badly damaged.				
12. Threats to the Propo	erty			
	√ NaturalNegligenceVandalismUrban Pressures			

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS