



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-355

SECTION I: IDENTIFICATION

1. Name

Present : Chandan Niwas
Past :
Other Name (if any):

2. Location /

LONGITUDE 75°15'E

LATITUDE 27°40'N

Address

Chandan Marg, Near Keshari Sagar, Ladanu

: Village (village code)

Post: Ladanu

District: Nagaur

State: Rajasthan

PIN: 341306

Approach

: The Haveli is situated near Keshari Sagar at Ladanu in Nagaur District. It is 90km away from Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input checked="" type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a triple story massive structure constructed with in a large walled complex. It has an arched gateway with beautiful carvings from top to bottom. All the three floors have separate architectural features. There is influence of European features at

the ground level where as the middle one has series of pointed arch openings and the upper most have semi circular arch. The

4. Property Use

ABANDONED ☒ IN USE

:

Present :

Past :

5. Age (Source)

PERIOD : 20th Century AD

YEARS :

Precise date of Construction :

Completion :

Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)

Private :

Any other (Please specify) :

Name :

Address :

Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :

Architect / Engineer :
Any other (specify) :

8. Statement of Significance

<input type="checkbox"/>	Architectural	:
<input type="checkbox"/>	Archaeological	:
<input type="checkbox"/>	Historical	:
<input type="checkbox"/>	Religious	:
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** * Drawings (Attach extra sheet if necessary)
 Urban√ / Rural Setting
 Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
 Area Dimension (L x B x H) : (m / cm/ feet / inch)
 Number of Blocks : 02
 Number of Storys : 02
- **Spatial Organization**
 Orientation : The Haveli is oriented North/South and faces the North.
 Plan :
 Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
 Exteriors :
 Interiors :
 Movable Collections :
Any Other (specify) :

10. Construction Technology

Structural System :
Building Techniques :

Material of Construction :

11. Condition Assessment

In General

Good / Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS