



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-362

SECTION I : IDENTIFICATION

1. Name

Present : Jhalria Mata
Past :
Other Name (if any):

2. Location

LONGITUDE 75°15' E

LATITUDE 27° 40' N

Address

Jhalra Mata Mandir, Dilwara

: Village (village code)

Post: Dilwara
State: Rajasthan

District: Nagaur
PIN: 341303

Approach district

: The Temple is situated, at Dilwara in Nagaur District. It is 100km away from bus stand Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

Religious structures

- ☐ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

Other Structures

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☒ Others (specify)
Math

Engineering structure

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

Open space and related structures

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

Note: It is a temple access through arches gateway. The gateway has series of foliated arch decorated with floral motif. It has a multistoried gateway divided into three levels. The uppermost level has projected balcony with feature like Bengali chhatri, jail work and brackets. Columns are

multiangular and cylindrical; The structure is surrounded with dome. On the either side of the balcony small door are beautifully decorated with creeper pattern. The arched gateway is followed by another gopuram style gateway. The spire of the gateway has sculpture of several cloistral gods and goddess. It has thee story with each level in having dwarpala in the middle guarding the miniature channel. The pattern of the gateway resembles north Indian style of temple architecture. On the top of the gateway it has seated celestial figure. The temple is entered through the gateway. It has large open and cloistered verandah. The mandapa is accessed through staircase. Three

4. Property Use

ABANDONED / IN USE ✓

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 17thCentury AD

YEARS :

Precise date of Construction :

Completion :

Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please
specify)state Govt.

Private :

Any other (Please specify) :

Name :

Address :

Phone :

7. Association

• **WITH EVENTS**

In History :

In Rituals : Living temple

In Building Construction :

Any other (specify) :

• **WITH PERSONS**

Patron :

Architect / Engineer :

Any other (specify) :

8. Statement of Significance

<input type="checkbox"/>	Architectural	Temple and gopurna style gateway
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

- **Context** * **Drawings** (Attach extra sheet if necessary)

Urban ✓/ **Rural Setting**

Surroundings

Stand in Isolation

Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks :

Number of Storys :

- **Spatial Organization**

Orientation : The Mata/Temple is oriented North/South and faces the South

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors :

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Rajasthan, Indo-Persian

Building Techniques : Arcuate system

Material of Construction : Stone, Bricks

11. Condition Assessment

In General

Good / Fair ✓

- | | |
|---|-------------------------|
| ✓ | Sign of Deterioration |
| | Serious Deterioration |
| | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Cluttered with wires and encroachment

12. Threats to the Property

- | | |
|---|-----------------|
| ✓ | Natural |
| | Negligence |
| | Vandalism |
| | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS