



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-410

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Shiv Mandir  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 40' N

#### Address

Shiv Mandir, Mundiya Talab, Mundiya

: **Village (village code)** Mundiya  
**Post** : Mundiya **District:** Nagaur  
**State** : Rajasthan **PIN:** 341028

#### Approach

: The Mandir is situated at Mundiya Talab, Mundiya. It is 25 k.m. away from Nagaur bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- |                          |                        |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace                 |
| <input type="checkbox"/> | Fort                   |
| <input type="checkbox"/> | Citadel                |
| <input type="checkbox"/> | Govt. building         |
| <input type="checkbox"/> | Railway station        |
| <input type="checkbox"/> | Defence building       |
| <input type="checkbox"/> | Industrial building    |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building   |

##### *Religious structures*

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple          |
| <input type="checkbox"/>            | Mosque          |
| <input type="checkbox"/>            | Minar           |
| <input type="checkbox"/>            | Church          |
| <input type="checkbox"/>            | Monastery       |
| <input type="checkbox"/>            | Stupa           |
| <input type="checkbox"/>            | Tomb, Mausoleum |

##### *Other Structures*

- |                          |                  |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall             |
| <input type="checkbox"/> | Gateway          |
| <input type="checkbox"/> | Pillar           |
| <input type="checkbox"/> | Others (specify) |

##### *Engineering structure*

- |                          |                             |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge                      |
| <input type="checkbox"/> | Tunnel                      |
| <input type="checkbox"/> | Other engineering structure |

##### *Open space and related structures*

- |                          |                |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square  |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard      |
| <input type="checkbox"/> | Baolis, Well   |
| <input type="checkbox"/> | Tank           |
| <input type="checkbox"/> | Cave           |

**Note:** The temple having an enclosure wall. It has foliated arch opening. The spandrel has floral motif. There is image of sitting Nandi facing towards the Linga and Linga is missing. The niches has the stone image of Hanuman.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** :  
**Past** :

#### 5. Age (Source)

---

**PERIOD** : 17<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of :  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Temple
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                         |
|-------------------------------------|---------------------|-------------------------|
| <input checked="" type="checkbox"/> | Architectural       | Foliated arch entrance. |
| <input type="checkbox"/>            | Archaeological      |                         |
| <input type="checkbox"/>            | Historical          |                         |
| <input type="checkbox"/>            | Religious           |                         |
| <input type="checkbox"/>            | Any other (specify) |                         |

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  

**\* Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H) :  

(m / cm/ feet / inch)

  
Number of Blocks : 01  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The Mandir is oriented East/West and faces the East  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Floral motifs, foliated arch  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- |                                 |   |                            |
|---------------------------------|---|----------------------------|
| <b>Structural System</b>        | : | Indo-Persian               |
| <b>Building Techniques</b>      | : | Arcuate system             |
| <b>Material of Construction</b> | : | Brick, Plaster, stone etc. |

### **11. Condition Assessment**

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/>            | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Peeling of plaster has exposed the core material, cracks.

## 12. Threats to the Property

---

<input checked="" type="checkbox"/>	Natural
<input checked="" type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**