

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-518

1. Name	SECTION I: IDENTIFICATION	I
Present Past Other Name (if any): 2. Location	: Bhairo Chock Well :	
LONGITUDE 75°15' E	LATITUDE 27° 40' N	
Address	Bhairo Chock, Kuchera : Village (village code)	Bahadana
Approach district		District: Nagaur PIN: 341024 near Bhairo Chock in Kuchera. and Nagaur. It is well connected
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify) Well
Engineering structure Bridge Tunnel Other engineering structure	Tank	Note: It is a beautiful well having typical Rajasthani architectural style generally found in Shekhawati region. It has canopied multi tired turrets built on the four corners separated by carving work. The plinth level has very good fortification like platform having series of multicusped

reached niches. All the four turrets joined with stone slabs attached together fitted with iron wheel for fetching the water.

4. Property Use

ABANDONED / IN USE

Present : Source of water Past : Source of water

5. Age (Source)

PERIOD : 18th century AD

YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private :

Any other (Please specify)
Name
Address

Phone :

7. Association

• WITH EVENTS

In History
In Rituals
In Building Construction
Any other (specify)

WITH PERSONS

Patron : Architect / Engineer : Any other (specify) :

8. Statement of Significance			
Architectural Archaeological ✓ Historical Religious Any other (specify)	Gigantic gateway with bastions		
SECTION II: DESCRIPTION			
 9. Physical Description and D Context Urban √ Rural Setting 	* Drawings (Attach extra sheet if necessary)		
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex		
Quantification Area Dimension (L x B x H)			
Number of Blocks Number of Storys	(m / cm/ feet / inch) : 01 : 01		
 Spatial Organization Orientation Plan Allocation of Spaces 	: The well is oriented east/west and faces the west :		
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : :		
10. Construction Technology			
Structural System Building Techniques Material of Construction	: : :		
11. Condition Assessment In General	Good / Fair √		
	Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary): Discoloration, weathering of stone surface, siltation etc.		
12. Threats to the Property	Natural Negligence Vandalism Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
	···
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS