

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-010

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Tara Bawari  
**Past** :  
**Other Name (if any):** :

#### 2. Location

##### LONGITUDE LATITUDE

**Address** Kumbhal Garh, Rajsamand

: **Village (village code)**  
**Post:** Kalwara **District:** Rajsamand  
**State:** Rajasthan **PIN:** 313325

**Approach district** : The Bawari is situated near by Ganesh Temple at Kumbhalgarh in Rajsamand district. It is 60km away from Rajsamand bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Engineering structure**

Bridge

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Open space and related structures**

Public square

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

**Note:** It is a rectangular step well cladded with rubble masonry. The well is in dilapidated condition. The staircases leading to the well are broken and a lot of Vegetational growth can be seen all around the monuments.

Tunnel  
 Other engineering structure

Park or garden  
 Graveyard  
 Baolis, Well  
 Tank  
 Cave

#### 4. Property Use

**ABANDONED  / IN USE**

**Present** : Not used for drinking purposes  
**Past** : Drinking

#### 5. Age (Source)

**PERIOD** : 16<sup>th</sup> Century AD  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

**SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. : A.S.I  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

##### •1 WITH EVENTS

**In History** :  
**In Rituals** :  
**In Building Construction** :  
**Any other (specify)** :

##### •2 WITH PERSONS

**Patron** :  
**Architect / Engineer** :  
**Any other (specify)** :

## 8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Rectangular step well.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features \_\_\_\_\_

●3 Context \* Drawings (Attach extra sheet if necessary)

Urban /  Rural Setting  
Surroundings

Stand in Isolation Integral part of a Landscape /  
Street / Complex

●4 Quantification

Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01

●5 Spatial Organization

Orientation : The Bawari is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

●6 Ornamentation

Exteriors : The step well is cladded with rubble masonry  
Interiors :  
Movable Collections :  
Any Other (specify) :

### 10. Construction Technology

Structural System : Step well made up of rubble masonry  
Building Techniques :  
Material of Construction : Rubble masonry.

## 11. Condition Assessment

In General

Good / Fair

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input type="checkbox"/>            | Sign of Deterioration   |
| <input checked="" type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):** Badly damaged.

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input type="checkbox"/>            | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input checked="" type="checkbox"/> | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

**13. Reference Sources** (published and unpublished textual details)

**14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference  
CAPTION**

**15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference  
DESCRIPTION**

**16. Maps/Plans/Drawings**

**17. Listers**

**NAME**

**NAME**

**18. Reviewers**

**NAME  
COMMENTS**

**NAME  
COMMENTS**