



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/RSD-020

### SECTION I: IDENTIFICATION

#### 1. Name

Present : Goswami Jee Ka Chhatri  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 74° 18'E

LATITUDE 26° 01'N

#### Address

Chattri, Bhilwara Road, Kankroli.

: **Village (village code)**

**Post:** Kankroli

**District:** Rajsamand

**State:** Rajasthan

**PIN:** 313324

#### Approach

: The Chattri is situated on the way to Bhilwara Kankroli in Rajsamand district. It is 1km away from Rajsamand bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### *Religious structures*

- ☐ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### *Other Structures*

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☒ Others (specify)- Chattri

##### *Engineering structure*

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### *Open space and related structures*

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** This is a Chhatri that stands abandoned and nearly dilapidated. This Chattri has no plinth or platform. Four thin pillars hold the small dome with a massive drum and steep caves. The ribs on the dome are unusual as they run diagonally.

---

**4. Property Use****ABANDONED / IN USE : ABADONED**

**Present** : Memorial  
**Past** : Chhatri

---

**5. Age (Source)**

**PERIOD** : 18<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

---

**6. Ownership / Level of Protection****SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of :  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

---

**7. Association**

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** : Made in the memory of a demised person.
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

---

**8. Statement of Significance**

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

:

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban √/ Rural Setting**  
**Surroundings**

\* **Drawings** (Attach extra sheet if necessary)  
setting

**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**

- **Quantification**

Area Dimension ( L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01  
Number of Storys : 01

- **Spatial Organization**

Orientation : The Chhatri is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**

Exteriors :  
Interiors :  
Movable Collections :

**Any Other** (specify) :

### **10. Construction Technology**

---

**Structural System** Indo-Persian.  
**Building Techniques** Arcuate system.  
**Material of Construction** Stone, Lime, Masonry

## 11. Condition Assessment

---

In General

Good ✓/ Fair

<input checked="" type="checkbox"/>	Sign of Deterioration
<input type="checkbox"/>	Serious Deterioration
<input type="checkbox"/>	Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Deep cracks developed in the dome and drum. The stone brackets have got defragment and displaced. Also there is a vegetational growth in around the structure. This Chattri is sheer victim of nelegence and vandalism.

---

## 12. Threats to the Property

<input checked="" type="checkbox"/>	Natural
<input checked="" type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**