



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/RSD-036

SECTION I: IDENTIFICATION

1. Name

Present : Maharaja Ki Chhatri.
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 18'E

LATITUDE 26° 01'N

Address

Near Nau Chawki, Rajsamand.

: **Village (village code)**

Post: Rajsamand

District: Rajsamand

State: Rajasthan

PIN: 313324

Approach

: The Chattri is situated at Nau Chawki in Rajsamand. It is 3km away from bus stand, Rajsamand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|---------------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify)- Chattri |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is built on a collapsed platform. This Chhatri is square in plan and has domical roofing. The drum has some patterns and the pillars are relatively plain and unpretentious.

4. Property Use**ABANDONED / IN USE :**

Present : Memorial
Past : Memorial

5. Age (Source)

PERIOD : 18th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection**SINGLE /MULTIPLE :**

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**

Urban √/ Rural Setting
Surroundings

*** Drawings** (Attach extra sheet if necessary)
setting

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 1
Number of Storys : 1

- **Spatial Organization**

Orientation : The Chhatri is oriented East/West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors : There are some geometrical patterns on the drum and on the capital of the pillars.

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System

Indo-Persian.

Building Techniques

Arcuate system.

Material of Construction

Stone, Lime Plaster, Rubble etc.

11. Condition Assessment

In General

Good ✓/ Fair

✓	Sign of Deterioration
✓	Serious Deterioration
✓	Danger of Disappearance

In Brief (Attach extra sheet if necessary):

This Chattri is in a sheer state of negligence. There is excessive accumulation of dirt, dust, root and wild growth on the dome and the drum along the enter surface of the Eaves. Also the plaster is peeling off. More Over the Surrounding is extremely polluted and future damaging the health of the structure.

12. Threats to the Property

✓	Natural
✓	Negligence
✓	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Gupta Dr.Mohan Lal, Udaipur Sambhag Ka Jilevar Sanskritik aur eatihasik adhayayan, Rajasthani Granthagar,Jodhpur, 2007-2009

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS