



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-070

SECTION I : IDENTIFICATION

1. Name

Present : Atithi Grihi(Kumbhal Garh Fort)
Past :
Other Name (if any): : Mehman Khana

2. Location

LONGITUDE 74°18'E

LATITUDE 24°01'N

Address

Kumbhal Garh ,Rajasmand

: **Village (village code)**

Post: Kelwara

District: Rajasmand

State: Rajasthan

PIN: 313325

Approach district

: The Structure is situated near Jain Temple at Kumbhal garh fort in Rajasmand district. It is 60km away from Rajasmand bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input checked="" type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is dilapidated structure. It has a number of pointed arch openings. Stories and bricks are scattered all over the place.

4. Property Use

ABANDONED/ IN USE ✓

Present : Tourist Site
Past : Historical Place/Palacial building

5. Age (Source)

PERIOD : 16th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of : A.S.I
India / State Archaeology
Department / Any Other (Please
specify)state Govt.

Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Pointed arch opening.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	

<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**

Urban /√ Rural Setting
Surroundings

*** Drawings** (Attach extra sheet if necessary)

Stand in Isolation

Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys : 01

- **Spatial Organization**

Orientation : The Structure is oriented East/West and faces the East.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors :

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : The dilapidated structure is made up of stone.

Building Techniques :

Material of Construction : Stone.

11. Condition Assessment

In General

Good / Fair

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Sign of Deterioration
Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary): Dilapidated.

12. Threats to the Property

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS