

### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

#### Documentation format for Archaeological and Heritage Sites / Monuments Serial No.: RJ/RSD-076 **SECTION I: IDENTIFICATION** 1. Name Present Pyau Wala Chhatri Past Other Name (if any): 2. Location 74°18'E LATITUDE LONGITUDE 26°01'N Address Main Bazaar, Nath Dwar Village (village code) Post: Nathdwara **District:** Rajsamand State: Rajasthan **PIN:** 313322 Approach The Chhatri is situated at Nathdwara in Rajsamand district. It is 17km away from Rajsamand bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify)-Chhatri Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is an octagonal Chhatri structures which is equitably carved. It has profusely carved pillars. Side by Bridge Public square side it has geometrical pattern Tunnel Park or garden over the dome. Other engineering structure Graveyard Baolis, Well

Tank Cave

| 4. Property Use                    |    | <b>ABANDONED</b> √/IN USE In use:              |
|------------------------------------|----|--|
| Present                            | :  | Memorial                                       |
| Past                               | :  | Memorial                                       |
| 5. Age (Source)                    |    |  |
| PERIOD                             | :  | 19 <sup>th</sup> Century AD                    |
| YEARS                              | :  |  |
| Precise date of Construction       | :  |  |
| Completion                         | :  |  |
| Subsequent changes                 | :  |  |
| Destruction / Demolition           | :  |  |
| 6. Ownership / Level of Protection | on |  |
|                                    |    | SINGLE /MULTIPLE :                             |
| Public: Archaeological Survey of   | :  |  |
| India / State Archaeology          |    |  |
| Department / Any Other (Please     |    |  |
| specify)                           |    |  |
| Private                            | :  |  |
| Any other (Please specify)         | :  |  |
| Name                               | :  |  |
| Address                            | :  |  |
| Phone                              | :  |  |
| 7. Association                     |    |  |
| WITH EVENTS                        |    |  |
| In History                         | :  |  |
| In Rituals                         | :  |  |
| In Building Construction           | :  |  |
| Any other (specify)                | :  | It is built in the memory of a demised person. |
| <ul> <li>WITH PERSONS</li> </ul>   |    |  |
| Patron                             | :  |  |
| Architect / Engineer               | :  |  |
| Any other (specify)                | :  |  |
| 8. Statement of Significance       |    |  |
| Architectural                      |    |  |
| Archaeological                     |    |  |
| Historical                         |    |  |
| Religious                          |    |  |
| Any other (specify)                |    |  |

### **SECTION II: DESCRIPTION**

### 9. Physical Description and Decorative Features

 Context Urban √/ Rural Setting

Surroundings

\* **Drawings** (Attach extra sheet if necessary)

Setting

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks 01 Number of Storys 01

Spatial Organization

Orientation The Chhatri is oriented East/West and faces the East.

Plan

Allocation of Spaces

**ARCHITECTURAL STYLE** 

Ornamentation

Exteriors The relief's carvings over the façade.

The interiors are carved and adorned with a variety of Interiors

design and motives.

Movable Collections

Any Other (specify)

10. Construction Technology

Structural System Indo-Persian. **Building Techniques** Arcuate system.

**Material of Construction** Stone, rubble masonry and lime plaster.

| 11. Condition Assessment     |  |
|------------------------------|--|
| In General                   | Good √/ Fair   |
|                              | Sign of Deterioration Serious Deterioration Danger of Disappearance                  |
| In Brief (Attach extra sheet | t if necessary): There is a mark of patina and accumulation of dirt                  |
| and dust.                    |  |
|                              |  |
| 12. Threats to the Property  |  |
|                              | <ul> <li>√</li> <li>√</li> <li>√</li> <li>Vandalism</li> <li>√</li> <li>✓</li> </ul> |

## **SECTION III:** REFERENCES

# 13. Reference Sources (published and unpublished textual details)

| 14. Photographs         |   |
|-------------------------|---|
|                         | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference         |   |
| CARTION                 |   |
| CAPTION                 |   |
| 15. Audio / Video       |   |
|                         | (related to rituals / performance / festivals etc.)         |
| Reference               |   |
| DESCRIPTION             |   |
| 16. Maps/Plans/Drawings |   |
|                         |   |
|                         |   |
|                         |   |
| 17. Listers             |   |
| NAME                    | NAME  |
| IVAIVIL                 | NAME  |
| 18. Reviewers           |   |
| NAME                    | NAME  |
|                         |   |
| COMMENTS                | COMMENTS  |