



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-088

SECTION I : IDENTIFICATION

1. Name

Present : Param Hans Dham
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 54'E

LATITUDE 24° 32' N

Address

Kulmbh Garh ,Rajasmand

: **Village (village code)**
Post: Kelwara **District:** Rajasmand
State: Rajasmand **PIN:** 313325

Approach district

: The Chhatri is situated near Jain Temple at Kumbhalgarh in Rajasmand district. It is 60km away from Rajasmand bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Other Structures

- | | |
|-------------------------------------|------------------------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify)
Chhatri |

Note: It is a canopied Chhatri having bulbous dome. The dome is surmounted by an inverted lotus type of pinnae. The dome is adorned with beautiful pattern.

4. Property Use

ABANDONED/ IN USE ✓

Present : Memorial
Past : Memorial

5. Age (Source)

PERIOD : 17th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

•1 WITH EVENTS

In History :
In Rituals :
In Building Construction :
Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

☒ Architectural
☐ Archaeological
☐ Historical

Dome having inverted lotus type of pinnae.

<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

•3 Context

Urban /√ Rural Setting

Surroundings

*** Drawings** (Attach extra sheet if necessary)

Stand in Isolation Integral part of a Landscape / Street / Complex

•4 Quantification

Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys : 01

•5 Spatial Organization

Orientation : The Chhatri is oriented East/West and faces the West.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

•6 Ornamentation

Exteriors : Beautiful design on the dome, The door has iron -grill fitting.

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Indo-Persian

Building Techniques : Arcuate

Material of Construction : Stone.

11. Condition Assessment

In General

Good / ☒ Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Blackening, peeling of plaster etc.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

**Photo Reference
CAPTION**

15. Audio / Video

(related to rituals / performance / festivals etc.)

**Reference
DESCRIPTION**

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

**NAME
COMMENTS**

**NAME
COMMENTS**