

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-109

1. Name	SECTION I: IDENTIFICATION	I	
Present Past Other Name (if any):	: Vedi Mandir :		
2. Location			
LONGITUDE 74° 18'E	LATIT	'UDE 26° 01' N	
Address	Vedi Temple Kumbhalgarh		
	: Village (village code) Post: Kelwara State: Rajasthan	District: Rajasmand PIN: 313325	
Approach district		at Kumbhalgarh in Rajasmand Rajasmand. It is well connected	
3. Property Type			
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures √ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure		Note: This is a beautiful temple with a massive domical roof built over a very high platform. The gate or toran dwar fitted to it having foliated arched openings. The main shrine having two sections.	
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well		

Tank
Cave

4. Property Use

ABANDONED / IN USE $\sqrt{}$

Present : Religious Past : Religious

5. Age (Source)

PERIOD : 15th Century AD

YEARS

Precise date of Construction Completion Subsequent changes Destruction / Demolition

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private : Any other (Please specify) : Name : Address : Phone :

7. Association

•1 WITH EVENTS

In History : In Rituals : In Building Construction : Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

Architectural
 i Architecturai

Archaeological Historical Religious Any other (specify)	:						
SECTION II: DESCRIPTION							
9. Physical Description and Decorative Features							
●3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)					
-		Stand in Isolation Integral part of a Landscape / Street / Complex					
•4 Quantification Area Dimension (L x B x H)	:						
Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01					
•5 Spatial Organization Orientation Plan Allocation of Spaces	: :	The Temple is oriented East/West and faces the East					
•6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : : :						
10. Construction Technology							
Structural System Building Techniques Material of Construction	: : :						

11. Condition Assessment	
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	t if necessary): Accumation of dust and dirt.
12. Threats to the Property	,
	Natural Negligence √ Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Gupta Dr.Mohan Lal, Udaipur Sambhag Ka Jilevar Sanskiritik aur eatihasik adhayayan, Rajasthani Granthagar, Jodhpur, 2007-2009

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS