

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.:RJ/RSD-114

#### **SECTION I: IDENTIFICATION** 1. Name **Present** Jain Mandir **Past** Other Name (if any): 2. Location LONGITUDE LATITUDE **Address** Kumbhal Garh Rajasmand Kulmbha Garh Village (village code) Post: Kalwara **District**: Rajasmand State: Rajasthan **PIN:** 313325 **Approach district** The Temple is situated at Kulbhagarh in Rajasmand district. It is 52km away from bus stand Rajasmand .It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is the remains of a structures temple. The top of the 'Garbhagriha'is missing. It stands on a raised platform. Public square Bridge Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank

Cave

#### 4. Property Use

Religious

Any other (specify)

# ABANDONED/ IN USE Present **Past** Religious 5. Age (Source) 17<sup>th</sup> Century AD **PERIOD YEARS Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection **SINGLE /MULTIPLE:** Public: Archaeological Survey of: India / State Archaeology Department / Any Other (Please specify)state Govt. **Private** Any other (Please specify) Name Address Phone 7. Association •1 WITH EVENTS In History In Rituals **In Building Construction** Any other (specify) •2 WITH PERSONS Patron **Architect / Engineer** Any other (specify) 8. Statement of Significance Architectural Remains of a temple. Archaeological Historical

## **SECTION II: DESCRIPTION**

9. Physical Description and Dec	cora	ative Features	
•3 Context Urban /√ Rural Setting Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary)	
		Stand in Isolation Integral part of a Landscape / Street / Complex	
•4 Quantification Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	01 01	
•5 Spatial Organization Orientation Plan Allocation of Spaces	: :	The Temple is oriented East/West and faces the West.	
•6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	No	
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	Temple made up of stone. (Nagara style of temple) Stone.	

11. Condition Assessment				
In General	Good / Fair			
	Sign of Deterioration  √ Serious Deterioration  Danger of Disappearance			
In Brief (Attach extra sheet if necessary): Badly damaged.				
12. Threats to the Property				
	<ul><li>√ Natural</li><li>Negligence</li><li>Vandalism</li><li>Urban Pressures</li></ul>			

### **SECTION III:** REFERENCES

13. Reference Sources	(published and unp	ublished textual	details)

**14. Photographs**(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS