

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-119

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any):	: Jain Mandir-3 :	
2. Location		
LONGITUDE 74° 54'E	LATITUDE	24° 32′ N
Address	Kulmgarh Rajasmand	
	: Village (village code) Post: Kulmgarh State: Rajasthan	District: Rajasmand PIN: 313325
Approach district	: The Temple is situated a Rajasmand district. It is It is well connected by re	60km away from Rajasmand.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures √ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure	structures s	lote: The temple is in a ruined tate. It has a dome. The upper tructure has been fallen off. Pillars are carved.
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank Cave	maro aro oarvoa.

4. Property Use

Architectural

Archaeological Historical Religious

Any other (specify)

ABANDONED / IN USE Present **Past** Religious 5. Age (Source) 16th Century AD **PERIOD YEARS Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection **SINGLE /MULTIPLE:** Public: Archaeological Survey of: India / State Archaeology Department / Any Other (Please specify)state Govt. **Private** Any other (Please specify) Name Address Phone 7. Association •1 WITH EVENTS In History In Rituals **In Building Construction** Any other (specify) •2 WITH PERSONS **Patron Architect / Engineer** Any other (specify) 8. Statement of Significance Pillars are chisselled and carved.

SECTION II: DESCRIPTION

9. Physical Description and De	ecorative Features
•3 Context Urban /√ Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary)
G	Stand in Isolation Integral part of a Landscape / Street / Complex

•4 Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

•5 Spatial Organization

Orientation : The Temple is situated North/South and faces the

South.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

•6 Ornamentation

Exteriors : Carved pillars, dome is without a pinnacle.

Interiors

Movable Collections : No

Any Other (specify) :

10. Construction Technology

Structural System : Indo-Islamic Building Techniques : Arcuate system

Material of Construction : Stone

11. Condition Assessment				
In General	Good√ / Fair			
	Sign of Deterioration Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sheet if necessary): Broken chhajjas, discoloration etc.				
12. Threats to the Property				
	√ NaturalNegligence√ VandalismUrban Pressures			

SECTION III: REFERENCES

13. Reference Sources	(published and unp	ublished textual	details)

14. Photographs(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS