



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-123

SECTION I : IDENTIFICATION

1. Name

Present : Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 54'E

LATITUDE 24° 32' N

Address Kulmgarh Rajasmand

: Village (village code)
Post: Kelwara District: Rajasmand
State: Rajasthan PIN: 313325

Approach district : The Temple is situated at Kelwara in Rajasmand district. It is 60km away from Rajasmand. It is well connected by regular bus services

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Note: The temple is dilapidated. Upper structure is missing. The door-lintel is intricately carved and ornamented. Dvar-palas at the entrance. The temple has sole leas relief.

☐ Cave

4. Property Use

ABANDONED / IN USE ✓

Present :
Past : Religious

5. Age (Source)

PERIOD : 16th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

•1 WITH EVENTS

In History :
In Rituals :
In Building Construction :
Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

☒ Architectural
☐ Archaeological

Intricately carved pattern rich in architectural embellishment.

<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

●3 **Context** * **Drawings** (Attach extra sheet if necessary)

Urban /√ Rural Setting
Surroundings

Stand in Isolation Integral part of a Landscape /
Street / Complex

●4 **Quantification**

Area Dimension (L x B x H) :
(m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys : 01

●5 **Spatial Organization**

Orientation : The Temple is situated East/West and faces the West.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

●6 **Ornamentation**

Exteriors : Adorned with socle bas relief ornamented door-lintel,
'Vardakas' at the entrance.

Interiors :

Movable Collections : No

Any Other (specify) :

10. Construction Technology

Structural System : Nagara style of temple

Building Techniques : Trabeate system

Material of Construction : Stone.

11. Condition Assessment

In General

Good / Fair

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Badly damaged.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

**Photo Reference
CAPTION**

15. Audio / Video

(related to rituals / performance / festivals etc.)

**Reference
DESCRIPTION**

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

**NAME
COMMENTS**

**NAME
COMMENTS**