



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-127

SECTION I : IDENTIFICATION

1. Name

Present : Partap Kund
Past :
Other Name (if any): :

2. Location

LONGITUDE LATITUDE

Address

Kulbh Garh Rajasmand

: **Village (village code)**
Post: Kalwara **District:** Rajasmand
State: Rajasthan **PIN:** 313325

Approach district : The Kund is situated near Jain Temple at Kelwara in Rajasmand district. It is 60km away from Rajasmand bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|-------------------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input checked="" type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a rectangular step well made up of stone and plaster. The well is not functional. It is full of stagnant and dirty water.

4. Property Use

ABANDONED / IN USE ✓

Present :
Past : Step well

5. Age (Source)

PERIOD : 17th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

•1 WITH EVENTS

In History :
In Rituals :
In Building Construction :
Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

✓	Architectural	Retangular step well.
	Archaeological	
	Historical	
	Religious	
	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

•3 Context

**Urban /√ Rural Setting
Surroundings**

*** Drawings** (Attach extra sheet if necessary)

**Stand in Isolation Integral part of a Landscape /
Street / Complex**

•4 Quantification

Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks :
Number of Storys :

•5 Spatial Organization

Orientation : The Kund is oriented North/South and faces the South
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

•6 Ornamentation

Exteriors :
Interiors :
Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Retangular step well made up of stone and plaster.
Building Techniques :
Material of Construction : Stone and plaster.

11. Condition Assessment

In General

Good /√ Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Peeling of plaster, deposition of sooth, Cracks, vegetational growth etc.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

**Photo Reference
CAPTION**

15. Audio / Video

(related to rituals / performance / festivals etc.)

**Reference
DESCRIPTION**

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

**NAME
COMMENTS**

**NAME
COMMENTS**