



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-130

SECTION I : IDENTIFICATION

1. Name

Present : Golerav Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 54'E

LATITUDE 24° 32' N

Address

Kulmbh Garh Rajasmand

: **Village (village code)**
Post: Kelwara **District:** Rajasmand
State: Rajasthan **PIN:** 313325

Approach district

: The Temple is situated at Kumbalgarh in Rajasmand district. It is 60km away from Rajasmand bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Engineering structure

- | | |
|--------------------------|--------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Note: The temple is of Nagara style having dome on the mandapa. The Shikar of the temple is badly damaged. The main shrine of the temple is leared on Trabeate system and Arcuate system for the mandapa. The temple can be approached by means of staircases which are in a damaged condition.

<input type="checkbox"/> Other engineering structure	<input type="checkbox"/> Graveyard
	<input type="checkbox"/> Baolis, Well
	<input type="checkbox"/> Tank
	<input type="checkbox"/> Cave

4. Property Use

ABANDONED/ IN USE ✓

Present :
Past : Religious

5. Age (Source)

PERIOD : 16th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of : A.S.I
 India / State Archaeology
 Department / Any Other (Please
 specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

•1 WITH EVENTS

In History :
In Rituals :
In Building Construction :
Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Dome on the mandapa
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

●3 Context * Drawings (Attach extra sheet if necessary)

Urban /☒ Rural Setting
Surroundings

**Stand in Isolation Integral part of a Landscape /
Street / Complex**

●4 Quantification

Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01

●5 Spatial Organization

Orientation : The Temple is oriented East/West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

●6 Ornamentation

Exteriors : Carved pillars
Interiors :
Movable Collections : No
Any Other (specify) :

10. Construction Technology

Structural System : Nagara style of temple having dome on the mandapa.
Building Techniques : Trabeate system for the main shrine and Arcuate system of for the mandapa.
Material of Construction : Stone.

11. Condition Assessment

In General

Good / Fair

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Badly Damaged

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

**Photo Reference
CAPTION**

15. Audio / Video

(related to rituals / performance / festivals etc.)

**Reference
DESCRIPTION**

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

**NAME
COMMENTS**

**NAME
COMMENTS**