

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-132

1. Name	SECTION I: IDENTIFICATION	i		
Present Past Other Name (if any):	: Bawari : :			
2. Location				
LONGITUDE 74° 54'E	LATITU	IDE 24° 32' N		
Address	Kumbhal Garh Rajasmand	Kumbhal Garh Rajasmand		
	: Village (village code) Post: Kalwara State: Rajasthan	District: Rajasmand PIN: 313325		
Approach district	Rajasmand district. It is	near Shiv temple at Kelwara in 60km away from Rajasmand nected by regular bus services.		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Temple Mosque Minar	Other Structures Wall Gateway Pillar Others (specify) Bawan		
Engineering structure	structures	Note: It is rectangular step well cladded with rubble masonry and lime-plaster. It can be approached by means of staircases. The walls and staircases have been broken. The well is full of dirty water. It is no -longer in use.		
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank	ge 		

4. Property Use

ABANDONED / IN USE

Present :

5. Age (Source)

PERIOD : 15th Century AD

YEARS :

Precise date of Construction Completion Subsequent changes Destruction / Demolition

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of : A.S.I

India / State Archaeology

nidia / Clate / ichacology

Department / Any Other (Please

specify)state Govt.

Private : Any other (Please specify) : Name : Address : Phone :

7. Association

•1 WITH EVENTS

In History : In Rituals : In Building Construction : Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Rectangular step well cladded with rubble masonry.
<u>S</u>	ECTION II: DESCRIPTION
9. Physical Description and Dec	corative Features
•3 Context Urban /√ Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary)
	Stand in Isolation Integral part of a Landscape $\sqrt{\ }$ / Street / Complex
 4 Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys 5 Spatial Organization Orientation Plan 	: (m / cm/ feet / inch) : : The Bawari is oriented East/West and faces the Best.
Allocation of Spaces ARCHITECTURAL STYLE •6 Ornamentation Exteriors Interiors	: :
Movable Collections Any Other (specify)	: :
10. Construction Technology	
Structural System Building Techniques Material of Construction	Rectangular step well cladded with rubble masonryStone and plaster.

11. Condition Assessment	
In General	Good /√ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	if necessary): Pilling of plaster, broken walls and staircases and
Vegetation growth.	
12. Threats to the Property	
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources	(published and unp	ublished textual	details)

14. Photographs(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS