

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/RSD-138

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any):	: Dam : : Embarkment	
2. Location		
LONGITUDE 74° 54'E	LATITUDE	24° 32′ N
Address	Kulmbh Gargh Rajasmand	
Approach district		District: Rajasmand PIN: 313325 Ilwara in Rajasmand district. It smand bus stand. It is well s services.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Mall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures si	ote: The wall is in a dilapidated tate Vegetational growth can be een all over the place.

4. Property Use

Religious

Any other (specify)

ABANDONED / IN USE **Present** Wall **Past** Wall 5. Age (Source) 17th Century AD **PERIOD** YEARS **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection **SINGLE /MULTIPLE:** Public: Archaeological Survey of : A.S.I India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association •1 WITH EVENTS In History In Rituals In Building Construction Any other (specify) •2 WITH PERSONS Patron **Architect / Engineer** Any other (specify) 8. Statement of Significance Architectural Wall made out of stone. Archaeological Historical

SECTION II: DESCRIPTION

9. Physical Description and Deco	orative Features	
●3 Context Urban √/ Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary)	
Garroundings	Stand in Isolation Integral part of a Landscape / Street / Complex	
●4 Quantification Area Dimension (L x B x H)	(m / om/foot / inch)	
Number of Blocks Number of Storys	(m / cm/ feet / inch)	
•5 Spatial Organization Orientation Plan Allocation of Spaces	The Wall is oriented North/South and faces the South	
ARCHITECTURAL STYLE		
Ornamentation Exteriors : Interiors : Movable Collections :		
Any Other (specify)		
10. Construction Technology		
Structural System Building Techniques	Wall made out of stone.	
Material of Construction	Stone.	

11. Condition Assessment				
In General Good / Fair				
	Sign of Deterioration Serious Deterioration √ Danger of Disappearance			
In Brief (Attach extra sheet if necessary): Dilapidated.				
12. Threats to the Property				
	Natural Negligence √ Vandalism Urban Pressures			

SECTION III: REFERENCES

13. Reference Sources	(published and unp	ublished textual	details)

14. Photographs(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS