



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/RSD-161

SECTION I : IDENTIFICATION

1. Name

Present : Unknown well
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 18' E

LATITUDE 26° 01' N

Address

Haldi Ghati, Near Chetak Samadhi

: **Village (village code)**

Post :

District: Rajasmand

State : Rajasthan

PIN:

Approach

: The Well is situated at Haldi Ghati. It is 40 k.m. away from Rajasmand bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

Religious structures

- ☐ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

Other Structures

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☒ Others (specify)
Well

Engineering structure

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

Open space and related structures

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

Note: This tank exist between two rubble masonry wells. It has no specific shape to be described. It is lined with stones

4. Property Use

ABANDONED / IN USE : Abandoned

Present :
Past :

5. Age (Source)

PERIOD : 18th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** : Water reservoir
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input type="checkbox"/>	Architectural	Cylindrical
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings

*** Drawings** (Attach extra sheet if necessary)
Urban

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks :
Number of Storys :

- **Spatial Organization**
Orientation : The Well is oriented East/West and faces the East
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Cylindrical
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- | | | |
|---------------------------------|---|------------------------|
| Structural System | : | Water reservoir |
| Building Techniques | : | Hydraulic system |
| Material of Construction | : | Stone & Rubble masonry |

11. Condition Assessment

In General	Good / Fair
	Good

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

This is an ill kept well. The water is polluted and unfit for use as its colour clearly suggests. There is development of mass over the boundary wall.

12. Threats to the Property

✓	Natural
✓	Negligence
✓	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS