

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/RSD-167 **SECTION I: IDENTIFICATION** 1. Name Present Halla Kund **Past** Other Name (if any): 2. Location 26⁰ 01 N LONGITUDE 740 18 E LATITUDE **Address** Near Halla Pol, Kambhalgarh Village (village code) Post: Kelwara District: Rajasmand State: Rajasthan PIN: 313325 Approach The Kund is situated Near Halla Pol. It is 60 k.m. away from Rajasmand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Kund Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is a small water tank structures lined with rubble masonry wall. Public square Bridge Tunnel Park or garden Graveyard Other engineering structure Baolis, Well Tank

Cave

4. Property Use		
	ABANDONED / IN USE: In use	
Present	•	
Past	:	
5. Age (Source)		
PERIOD	: 15 th Century A.D.	
YEARS	: 13 Century A.D.	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection		
	SINGLE /MULTIPLE :	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Archaeological Survey of India	
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	•	
7. Association		
WITH EVENTS In History	: Water reservoir	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS Patron		
Architect / Engineer	•	
Any other (specify)	:	
, , , , , ,		
8. Statement of Significance		
Architectural	Water reservoir	
Archaeological		
Historical		
Religious Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban	
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex	
• Quantification Area Dimension (L x B x	H) : (m / cm/ feet / inch)	
Number of Blocks Number of Storys	(III / GIII/ ICCL / IIIGII) :	
 Spatial Organization Orientation Plan Allocation of Spaces 	: The Kund is oriented North/South and faces the North:	
ARCHITECTURAL STYLE		
Ornamentation Exteriors Interiors Movable Collections	: Plain & simple with thick masonry walls :	
Any Other (specify)	· :	
10. Construction Technolog	у	
Structural System Building Techniques Material of Construction	: Water reservoir: Hydraulic system: Stone & rubble masonry.	
11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance	e	
In Brief (Attach extra sheet	if necessary):	

The water is extremely polluted as the colour of the water clearly suggest. Also there is dumped garbage in and around the tank. Also there are small plants that are growing in the small gaps in the stone masonry

12. Threats to the Property

✓ Natural
✓ Negligence
✓ Vandalism
✓ Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS