

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR – 12

1. Name	SECTION I: IDENTIFICATION	
Present Past	: Madhav Kalyan Singh ka Well	_
Other Name (if any):	:	
2. Location		
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 [°] N	
Address	Nalka Well, Ward No. 11, near Surajpole.	
	: Village (village code) Post : Sikhar District: Sikhar State : Rajasthan PIN: 332001	
Approach	: The Well is situated in Sikar located near Suraj Pole, Sikar, 1 k.m. from Railway Station.	
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum	
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: A square shaped well with masonry structures is seen two octagonal turrets with chhajja, drum and dome is present in the front together with two octagonal minars of lower height nearby.✓Baolis, WellTank CaveCave) , ;

4. Property Use				
		ABANDONED / IN USE : Abandoned		
Present	:	Dry		
Past	:	Source of drinking water		
5. Age (Source)				
PERIOD	•			
YEARS	:	20 th Century A.D.		
Precise date of Construction	:			
Completion	:			
Subsequent changes	:			
Destruction / Demolition	:			
0. Our and in (1 and a) Decisation				
6. Ownership / Level of Protection	n			
		SINGLE /MULTIPLE :		
Public : Archaeological Survey of	:	Not protected		
India / State Archaeology		•		
Department / Any Other (Please				
specify)				
Private	:	Madhav Kalyan Singh ji.		
Any other (Please specify)	:	, , ,		
Name	:			
Address	:			
Phone	:			
7. Association				
WITH EVENTS				
In History	:	In History		
In Rituals	:			
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS				
Patron	:	Madhav Kalyan Singhji		
Architect / Engineer	:			
Any other (specify)	:			
8. Statement of Significance				

Architectural
 Archaeological
 ✓ Historical
 Religious
 Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban
Carrounango	Stand in Isolation Integral part of a Landscape / Street / Complex Complex
• Quantification Area Dimension (L x B x H)	
Number of Blocks Number of Story's	(m / cm/ feet / inch)
 Spatial Organization Orientation Plan Allocation of Spaces 	 The Well is oriented East – West and faces the West Square shape
ARCHITECTURAL STYLE Ornamentation	
Exteriors	: Two octagonal turrets with octagonal chajja, drum and dome is seen. Moreover two octagonal minars of shorter height with octagonal chhajja, drum and dome is also present.
Interiors Movable Collections	: A Shivalinga inside a rectangular small temple nearby is seen.
Any Other (specify) 10. Construction Technology	: :
Structural System Building Techniques Material of Construction	 Brick Masonry, elements of Indo-Islamic Corbelling Bricks, cement, mortar, tiles, rod
11. Condition Assessment	
In General G	Good / Fair

Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Cracks are seen along with algae problem. Negligence and human vandalism is quite prominent.

12. Threats to the Property

	Nat
<	Neg
<	Van
	Urb

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	_
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS