



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR - 112

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Chhagan Lal Kishan Lal Poddar Ki Haveli  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 36' N

#### Address

Near Ashram Temple, Ward no -20, Chhatri Bus Stand

: **Village (village code)**

**Post** : Fatehpur

**District**: Sikar

**State** : Rajasthan

**PIN**: 332301

#### Approach

: The Haveli is situated in Fatehpur located near Ashram Temple and 100 KM from Chhatri Bus Stand. It is 42 KM from Sikar bus stand and well connected by regular bus services from big cities.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a single residential building with the huge wooden door and lots of paintings on the walls. The bracket and chhaja is also carved and decorated.

#### 4. Property Use

---

**ABANDONED / IN USE :** Abandoned

**Present** : Locked  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- Context** : **\* Drawings** (Attach extra sheet if necessary)
- Urban / Rural Setting** : Urban
- Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**

- Quantification**

- Area Dimension ( L x B x H) : \_\_\_\_\_ (m / cm/ feet / inch)
- Number of Blocks : 02
- Number of Story's : 02

- Spatial Organization**

- Orientation : The Haveli is oriented East – West and faces the East.
- Plan :
- Allocation of Spaces :

### ARCHITECTURAL STYLE

- Ornamentation**

- Exteriors : The Chhaja with carved brackets and paintings on the walls are nice and visible.
- Interiors :
- Movable Collections :
- Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : The chhaja with carved brackets and paintings on the walls are nice and visible.
- Building Techniques** : Arcuate
- Material of Construction** : Brick, lime, cement, brick jeera, stone etc.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**  
Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

The paintings of the building is almost gone and need conservation work to be done.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(Attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(Related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

**NAME**

**NAME**

#### **18. Reviewers**

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**