

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments			
1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/SKR-134	
Present Past Other Name (if any): 2. Location	: Bubana Ka Haveli : :		
LONGITUDE 75° 15' E Address	LATITUDE 27 ⁰ 36 [°] N Sankari Gali, Ward No.16		
Approach 3. Property Type		District: Sikar PIN: 338301 in Sankari gali at Fatehpur rom Sikar and well connected	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure Bridge Tunnel Other engineering structure	structures r. Public square a	Note: It is a haveli built on a light aised platform of red sand stone and with the beautiful tile work on the door has nice carving.	

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD		
YEARS	:	19 th Century A.D.
Precise date of Construction	:	19 Octivity A.D.
Completion	•	
Subsequent changes	:	
Destruction / Demolition	•	
	-	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and	Decorative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex
 Quantification Area Dimension (L x B x I 	f) : (m / cm/ feet / inch)
Number of Blocks Number of Storys	: 02 : 01
 Spatial Organization Orientation Plan Allocation of Spaces 	The Haveli is oriented East-West and faces the East:
ARCHITECTURAL STYLE	
 Ornamentation Exteriors 	 Beautiful tile and painting work done on the foliated arches of the haveli. Also the carving of door is beautiful.
Interiors Movable Collections Any Other (specify)	: : :
10. Construction Technolog	<i>I</i>
Structural System	: The single storey structure has a flat roof with the chajja and brackets.
Building Techniques	 The building has long window and has a beautiful carving on it. Built on a height with the plinth of red sand stone.
Material of Construction	: Brick, brick jeera, lime, red sand stone cement.
11. Condition Assessment	
In General	Good / Fair – good
Sign of Deterioration Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet i	

in Brief (Attach extra sneet if necessary):

The haveli is maintained in good manner but some sign of deterioration is clearly visible.

12. Threats to the Property	
	✓ Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS