


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-162

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Jaidev Babulal Saraf ki haveli. :
LONGITUDE 75 ⁰ 15 ['] E	LATITUDE 27 ⁰ 36 ['] N
Address	Sodawara, Fatehpur Shekhawati, Ward No.11
	: Village (village code) Post : Fatehpur District: Sikar State : Rajasthan PIN: 332301
Approach	 The Haveli is situated near Sadawara of Fatehpur. It is 42 km from Sikar and well connected by regular bus services.

3. Property Type



4. Property Use

		ABANDONED / IN USE : Abandoned
Present Past	:	Residence
5. Age (Source)		
PERIOD		
YEARS	÷	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
✓ Architectural	Dr	Dressed stone
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)	
	Number of Blocks Number of Storys	:	01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented East-West and faces the East.	
<u>A</u> •	RCHITECTURAL STYLE Ornamentation Exteriors	:	A parapet wall on top of the haveli has geometrical designs. It has projected chhajjas supported by stone	
Ar	Interiors Movable Collections ny Other (specify)	:	brackets.	

10. Construction Technology

Structural System	:	Indo -Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone.

11. Condition Assessment

In General

Good / Fair - Good

Sign of Deterioration

Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening and peeling of plaster.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS