

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-167

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any):	Seth Khetan ka well		
2. Location			
LONGITUDE 75 ⁰ 15 [°] E	LATITUDE 27 ⁰ 36 ['] N		
Address	Jalana Jaw Fatehpur, Ward No.35		
	: Village (village code) Post : Fatehpur District: Sikar Sekhwati State : Rajasthan PIN: 332301		
Approach	: The well is situated near by chhatri bus stand at Fatehpur Sekhawati. It is well connected by regular bus services.		

3. Property Type



	ABANDONED / IN USE : Abandoned
Present	: Dryed up
Past	: Source of drinking water.
5. Age (Source)	
PERIOD	:
YEARS	: 20 th Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	
Architect / Engineer	
Any other (specify)	
	•
8. Statement of Significance	
✓ Architectural	Rubble masonry and dressed stone
Archaeological	
Historical	
Religious	
Any other (specify)	

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation		
			Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The well is oriented North-South & faces to the South		
<u>A</u> [•	RCHITECTURAL STYLE Ornamentation Exteriors	:	The well rests on a raised platform. It is surrounded by four octagonal pillars having inverted lotus type of		
Aı	Interiors Movable Collections ny Other (specify)	:	pinnacle.		

10. Construction Technology

Structural System	:	Indo –Persian
Building Techniques	:	Brick masonry
Material of Construction	:	Brick and stone.

11. Condition Assessment

In General

Good / Fair - Good

 \checkmark

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plaster and blackening.

12. Threats to the Property

	Nat
<	Neg
	Var
	Urb

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS