


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-171

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	Chiranjivi lal Durga ki haveli
2. Location	
LONGITUDE 75 ⁰ 15 [°] E	LATITUDE 27 ⁰ 36 [°] N
Address	Near by Dugar School, ward no.13
	: Village (village code) Post : Fatehpur District: Sikar Sekhawat State : Rajasthan PIN: 332301
Approach	 The haveli is situated 42 km far from Sikar. It is well connected by regular bus and train services from well known places.

3. Property Type



4. Property Use				
	ABANDONED / IN USE : In use			
Present	:	Resid	dence	
Past	:	: Residence		
5. Age (Source)				
PERIOD	:			
YEARS	:	19 th	Century A.D.	
Precise date of Construction	:			
Completion	:			
Subsequent changes	:			
Destruction / Demolition	:			
6. Ownership / Level of Protecti	on			
	SINGLE /MULTIPLE :			
Public : Archaeological Survey of	:			
India / State Archaeology				
Department / Any Other (Please				
specify)				
Private	:			
Any other (Please specify)				
Name				
Address				
Phone	:			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	•			
In Building Construction				
Any other (specify)	:			
WITH PERSONS	•			
Patron				
Architect / Engineer	:			
Any other (specify)	:			
Any other (specify)	•			
8. Statement of Significance				
 ✓ Architectural 	dre	essed st	tone	
Archaeological				
Historical				

Religious
Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban		
			Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	02 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The haveli is oriented East-West and faces to the West.		
<u>A</u> •	RCHITECTURAL STYLE Ornamentation Exteriors	:	The ceiling of the chhajjas and stone brackets are painted with yellow colour. The vault of the arch is painted green. Alcours can be seen inside the haveli.		
Aı	Interiors Movable Collections y Other (specify)	:			

10. Construction Technology

Structural System	:	Indo –Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick and stone.

11. Condition Assessment

In General

Good / Fair - Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS