



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR - 215

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Ulanga Mata Temple ka well  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 36' N

#### Address

Ulanga mata temple complex, Ward no -15

: **Village (village code)**

**Post** : Fatehpur Sekhwati **District**: Sikar

**State** : Rajasthan **PIN**: 332301

#### Approach

: The Well is situated at Fatehpur Shekhawati wait which is 500M from Chhatri bus stand & 42 KM from Sikar and well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is an octagonal well cladded with rubble masonry. The well is surrounded by four octagonal pillars having an inverted lotus type of pinnacle. The well rests on a raised platform. The well can be commercial and residential buildings near vicinity.

#### 4. Property Use

---

**ABANDONED / IN USE :** Abandoned

**Present** : Dry  
**Past** : Source of Drinking Water

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                 |
|-------------------------------------|---------------------|-----------------|
| <input checked="" type="checkbox"/> | Architectural       | Rubble masonry. |
| <input type="checkbox"/>            | Archaeological      |                 |
| <input type="checkbox"/>            | Historical          |                 |
| <input type="checkbox"/>            | Religious           |                 |
| <input type="checkbox"/>            | Any other (specify) |                 |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)
  - Urban / Rural Setting** : Rural
  - Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**
  - Area Dimension ( L x B x H) : (m / cm/ feet / inch)
  - Number of Blocks : 01
  - Number of Story's : 01
  
- **Spatial Organization**
  - Orientation : The well is oriented East – West and faces the East.
  - Plan :
  - Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**
  - Exteriors : Four octagonal pillars having an inverted lotus type of pinnacle surround the well.
  - Interiors : The well is clad with rubble masonry.
  - Movable Collections :
  - Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo Persian
- Building Techniques** : Brick Masonry
- Material of Construction** : Brick & Stone.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Blackening and vegetation growth.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input type="checkbox"/>            | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(Attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(Related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

**NAME**

**NAME**

#### **18. Reviewers**

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**