


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-226

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any): 2. Location	Puranmal Rameshwar Saraswat ji ki Haveli		
LONGITUDE 75° 15 [°] E	LATITUDE 27 [°] 36 [°] N		
Address	Near Post Office, Ward No. 27		
	: Village (village code) Post : Fatehpur District: Sikar Sekhawati State : Rajasthan PIN: 332301		
Approach	: The Haveli is situated 40 km from Sikar & well connected by regular bus services from big cities.		

3. Property Type



		ABANDONED / IN USE : In use
Present	: R	esidence
Past		esidence
5. Age (Source)		
PERIOD		
YEARS	. 10	th Century A.D.
Precise date of Construction		
Completion		
Subsequent changes		
Destruction / Demolition	:	
C. Oursenskin (Lough of Drotestic		
6. Ownership / Level of Protection	on	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology	•	
Department / Any Other (Please		
specify)		
Private	-	
Any other (Please specify)		
Name		
Address		
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer		
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)	
	Number of Blocks Number of Storys	:	01 02	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented East-West & faces the East.	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		The railings are supported by bracketed parapet.	

SECTION II: DESCRIPTION

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate
Material of Construction	:	Stone, rubble masonry etc.

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Seepage, blackening, fading on exterior walls, interior encroachment & ill maintained.

12. Threats to the Property

<	Na
<	Ne
	Va
\checkmark	Urk

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS