

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/SKR-239

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Balajee Ka Temple :
2. Location	
LONGITUDE 75 <sup>0</sup> 15 <sup>'</sup> E	LATITUDE 27 <sup>0</sup> 36 <sup>°</sup> N
Address	Shree Punrajjee Ka Sahram, B.D. Todi College Lacchmangarh
	: Village (village code) Post : Laxmangarh District: Sikar State : Rajasthan PIN: 332311
Approach	The Temple is situated 22 km from Sikar Bus Stand & 20 Km from Fatehpur.
3. Property Type	

 Buildings	Religious structures	Other Structures
Palace	✓ Temple	Wall
Fort	Mosque	Gateway
Citadel	Minar	Pillar
Govt. building	Church	Others (specify)
Railway station	Monastery	
Defence building	Stupa	
Industrial building	Tomb, Mausoleum	
Other public buildings		
Residential building		
Engineering structure	Open space and related structures	<b>Note:</b> This is a simple structure raised on a slight platform. It has
Engineering structure Bridge		<b>Note:</b> This is a simple structure raised on a slight platform. It has porch like balcony all around
	structures	raised on a slight platform. It has
Bridge	<i>structures</i> Public square	raised on a slight platform. It has porch like balcony all around
Bridge Tunnel	structures Public square Park or garden	raised on a slight platform. It has porch like balcony all around followed by rooms. Over the terrace there is an octagonal chhatris with a domical roof. This
Bridge Tunnel	structures         Public square         Park or garden         Graveyard	raised on a slight platform. It has porch like balcony all around followed by rooms. Over the terrace there is an octagonal chhatris with a domical roof. This chattri is painted & has scenes
Bridge Tunnel	structures         Public square         Park or garden         Graveyard         Baolis, Well	raised on a slight platform. It has porch like balcony all around followed by rooms. Over the terrace there is an octagonal chhatris with a domical roof. This chattri is painted & has scenes inside i.e. along the moulding of
Bridge Tunnel	structures         Public square         Park or garden         Graveyard         Baolis, Well         Tank	raised on a slight platform. It has porch like balcony all around followed by rooms. Over the terrace there is an octagonal chhatris with a domical roof. This chattri is painted & has scenes

		ABANDONED / IN USE : In use
Present	: F	Religious activity
Past		Religious
5. Age (Source)		
PERIOD	:	
YEARS	: 1	8 <sup>th</sup> Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address		
Phone	:	
7. Association		
WITH EVENTS		
In History	•	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	_	
Patron	-	
Architect / Engineer	-	
Any other (specify)	•	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		

9.	9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)	
	Number of Blocks Number of Storys	:	01 01	
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The Temple is oriented East - West & faces the East.	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections	:		
Ar	<b>y Other</b> (specify)	•		

## **10. Construction Technology**

	:	Indo – Persian Arcuate Stopo, Rubble Maconny, Bricks, Comont etc.
waterial of Construction	•	Stone, Rubble Masonry ,Bricks, Cement etc.

#### 11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Fading of painted layer.

## 12. Threats to the Property

$\checkmark$	Na
$\checkmark$	Ne
$\checkmark$	Va
$\checkmark$	Ur

Natural Negligence Vandalism Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS