

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-242

1. Name	SECTION I: IDENTIFICATION			
Present Past Other Name (if any):	: Mirja Subh Kananki House :			
2. Location				
LONGITUDE 75° 15' E LATITUDE 27° 36' N				
Address	Mori Gate, Lacchemangarh, Ward No -23			
Approach	 Village (village code) Post : Laxmangarh State : Rajasthan District: Sikar PIN: 332311 The Building is situated 22 km from Sikar Bus Stand 8 			
Approach	 The Building is situated 22 km from Sikar Bus Stand & 20 Km from Fatehpur. 			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings ✓	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote:This is an old Jadea building with foliated arched gateway & terrace railings rested on the bracketed parapet. The gateway is adorned with floral pattern & worshipers. The portion beneath the parapet is also painted. The entire façade is painted with procession scenes 			

	ABANDONED / IN USE : In use
Present	: Residence
Past	: Residence
5. Age (Source)	
PERIOD	:
YEARS	: 20 th Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological	
Historical	
Religious	
Any other (specify)	

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)		
	Carroundingo		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	02 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Building is oriented East-West & faces the East.		
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: :	The columns used is grey, brown, red, yellow, green etc.		

SECTION II: DESCRIPTION

10. Construction Technology

ry, lime plaster.
ry

11. Condition Assessment

In General

Good / Fair

✓

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It is in a poor state. Faded paintings. Unaesthetic renovation.

12. Threats to the Property

\checkmark	Na
\checkmark	Ne
\checkmark	Va
\checkmark	Ur

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS