

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-247

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: Gananand Jalan Bark Ki Haveli :		
LONGITUDE 75° 15 [°] E	LATITUDE 27° 36' N		
Address	Gajanand Jalan Bark, Mori gate, Ward No -29		
	: Village (village code) Post : Laxmangarh State : Rajasthan PIN: 332311		
Approach	 The Haveli is situated 22 km from Sikar bus stand & 20 km from Fatehpur & well connected by regular bus services from big cities. 		

3. Property Type

	Buildings	Religious structures	Other Structures
	Palace	Temple	Wall
	Fort	Mosque	Gateway
	Citadel	Minar	Pillar
	Govt. building	Church	Others (specify)
	Railway station	Monastery	
	Defence building	Stupa	
	Industrial building	Tomb, Mausoleum	
	Other public buildings		
\checkmark	Residential building		
	Engineering structure	Open space and related structures	Note: This two floored building is raised on a high platform with
		structures	raised on a high platform with
	<i>Engineering structure</i> Bridge Tunnel	structures Dublic square	
	Bridge Tunnel	structures Public square Park or garden	raised on a high platform with foliated arched gateway which is
	Bridge	structures Dublic square	raised on a high platform with foliated arched gateway which is shaded by asbestos. The gateway has floral painting & portraits on the façade beneath the parapet
	Bridge Tunnel	structures Public square Park or garden Graveyard	raised on a high platform with foliated arched gateway which is shaded by asbestos. The gateway has floral painting & portraits on the façade beneath the parapet between the brackets. The façade
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well	raised on a high platform with foliated arched gateway which is shaded by asbestos. The gateway has floral painting & portraits on the façade beneath the parapet between the brackets. The façade has small arched window with
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	raised on a high platform with foliated arched gateway which is shaded by asbestos. The gateway has floral painting & portraits on the façade beneath the parapet between the brackets. The façade has small arched window with cupola shaped reliefs. On two side
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	raised on a high platform with foliated arched gateway which is shaded by asbestos. The gateway has floral painting & portraits on the façade beneath the parapet between the brackets. The façade has small arched window with

		ABANDONED / IN USE : In use
Present	:	Residence
Past	-	Residence
	•	
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
9 Statement of Circuitions		
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious Any other (specify)		

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m/om/fact/inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented East-West & faces the West.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)		Colour- Red, Yellow, green, blue etc.

SECTION II: DESCRIPTION

10. Construction Technology

Structural System	:	Indo – Persian
Building Techniques	:	Arcuate
Material of Construction	:	Stone, rubble masonry, bricks etc

11. Condition Assessment

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Cement & plaster are peeling of the façade. Accumulation of dirt & dust.

12. Threats to the Property

\checkmark	Na
\checkmark	Ne
\checkmark	Va
\checkmark	Ur

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS