

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-255

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Kedia ka Well :	
2. Location		
LONGITUDE 75° 15 [°] E	LATITUDE 27° 36' N	
Address	Near Sitla Mata Ka Temple, Ward No -29	
Approach	 Village (village code) Post : Laxmangarh District: Sikar State : Rajasthan PIN: 332311 The Well is situated near Sitla Mandir & 22km fr Sikar bus stand. 	om
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum	
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Note: Raised on a platform well has two towers and stumps to support the p device. The lining, inside the v in unplastered and has a ladder inside it. ✓ Baolis, Well ladder inside it.	two oully well

		ABANDONED / IN USE : Abandoned
Present	:	Not used for drinking purpose
Past	:	Used for drinking purposes
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address		
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
9. Statement of Significance		
8. Statement of Significance		
Architectural Archaeological		
Historical		
Religious		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary)
j.		Stand in Isolation Integral part of a Landscape / Street / Complex
Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
Number of Blocks Number of Storys	:	
 Spatial Organization Orientation Plan Allocation of Spaces 	:	The Well is oriented East – West & faces the West.
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	:	Plain and simple

10. Construction Technology

Structural System Building Techniques		Indo – Persian Arcuate
Material of Construction	:	Stone, rubble masonry.

11. Condition Assessment

In General

Good / Fair

✓

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The lining inside the well is exposed. Lacks general maintenance.

12. Threats to the Property

	Nat
<	Neg
	Var
	Urb

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS