

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-258 **SECTION I: IDENTIFICATION** 1. Name Present Haveli Past Other Name (if any): 2. Location 27⁰ 36' N LONGITUDE 75° 15' E LATITUDE **Address** Near Agrasen Bhawan, Ward No. 26 Village (village code) Post: Laxmangarh District: Sikar State: Rajasthan **PIN:** 332311 Approach The Haveli is situated near Agrasen Bhawan & 22 k.m. from Sika Bus Stand. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Tomb, Mausoleum Industrial building Other public buildings Residential building Engineering structure Open space and related Note: Raised on a platform the structures facade of the building is very Bridge Public square European in its treatment. It has Park or garden round arched opening Tunnel screened panels & portraits in the Other engineering structure Graveyard centre of it. Baolis, Well Tank

Cave

4. Property Use			
		ABANDONED / IN USE :	Abandoned
Present	:	Locked	
Past	:	Residence	
5. Age (Source)			
PERIOD	•		
YEARS	:	20 th Century A.D.	
Precise date of Construction	:	,	
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6 Ownership / Lovel of Protection	on.		
6. Ownership / Level of Protection	<i>)</i>		
		SINGLE /MULTIPLE :	
Public: Archaeological Survey of	:		
India / State Archaeology			
Department / Any Other (Please			
specify)			
Private	:		
Any other (Please specify) Name	:		
Name Address	•		
Phone	:		
i none	•		
7. Association			
 WITH EVENTS 			
In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:		
WITH PERSONS			
Patron	:		
Architect / Engineer	:		
Any other (specify)	i		
9 Statement of Significance			
8. Statement of Significance			
Architectural			
Archaeological			
Historical Religious			
Any other (specify)			

SECTION II: DESCRIPTION

9. l	Physical Description and D	ecora	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)) :	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Haveli is oriented East – West & faces the West.
<u>AR</u>	CHITECTURAL STYLE Ornamentation Exteriors	:	The railings to the terrace is also severed. But has arched door.
An	Interiors Movable Collections y Other (specify)	: : :	
10.	Construction Technology		
	Structural System Building Techniques Material of Construction	:	Indo – Persian & European Corbelled, English bond. Bricks, cement, lime plaster etc.
11.	Condition Assessment		
	In General	Good	/ Fair
√	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In l	Brief (Attach extra sheet if	neces	ssarv):

Excessive cracks & peeling of plaster, Blackening, Accumulation of dirt & dust.

12. Threats to the Property

✓ Natural✓ Negligence✓ Vandalism✓ Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS
LALIMINICIALIA	CACIVITIES 1.3