

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-263

| 1. Name | SECTION I: IDENTIFICATION | |
|---|--|--|
| Present Past Other Name (if any): | : Gokuldas ka Well : : | |
| 2. Location | | |
| LONGITUDE 75° 15' E | LATITUDE 27° 36' N | |
| Address | Pakki Piwari, Station Road, Ward No. 15 | |
| Approach | Village (village code) Post : Laxmangarh State : Rajasthan The Well is situated at Lacchmangarh in Station Road & about 21 k.m. from Sikar Bus Stand. | |
| 3. Property Type | | |
| Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building | Religious structures Other Structures Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum Difference | |
| Engineering structure Bridge Tunnel Other engineering structure | Open space and related structuresNote: Raised on a slight platform the square well has four towers to support its pulley device. The towers are lofty and is painted along the flake & on the mouldings. The roofing is a domical one with reliefs over it. The drainage which runs out the wall carries the water to a bigger tank. | |

| | ABANDONED / IN USE : Abandoned |
|------------------------------------|---------------------------------|
| | |
| Present | : Not used for drinking water |
| Past | : Used for drinking water |
| 5. Age (Source) | |
| PERIOD | : |
| YEARS | : 20 th Century A.D. |
| Precise date of Construction | : |
| Completion | : |
| Subsequent changes | : |
| Destruction / Demolition | : |
| 6. Ownership / Level of Protection | on |
| | SINGLE /MULTIPLE : |
| Public : Archaeological Survey of | : |
| India / State Archaeology | |
| Department / Any Other (Please | |
| specify) | |
| Private | : |
| Any other (Please specify) | : |
| Name | : |
| Address | : |
| Phone | : |
| 7. Association | |
| WITH EVENTS | |
| In History | : |
| In Rituals | : |
| In Building Construction | : |
| Any other (specify) | |
| WITH PERSONS | |
| Patron | |
| Architect / Engineer | : |
| Any other (specify) | : |
| Any other (specify) | • |
| | |
| 8. Statement of Significance | |
| Architectural | |
| Archaeological | |
| Historical | |
| Religious | |
| Any other (specify) | |

| 9. Physical Description and Decorative Features | | | |
|--|---|--|--|
| Context Urban / Rural Setting Surroundings | * Drawings (Attach extra sheet if necessary) | | |
| | Stand in Isolation Integral part of a Landscape / Street / Complex | | |
| Quantification Area Dimension (L x B x H) : | (m / cm/ feet / inch) | | |
| Number of Blocks : Number of Storys : | | | |
| Spatial Organization Orientation Plan Allocation of Spaces | The Well is oriented East – West & faces the West. | | |
| ARCHITECTURAL STYLE | There is a mesh work on the surface of the tower. | | |

10. Construction Technology

11. Condition Assessment

In General

Good / Fair

✓ _____ Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening, accumulation of dirt & dust, breakage is claded slabs.

12. Threats to the Property

| \checkmark | Na |
|--------------|----|
| \checkmark | Ne |
| \checkmark | Va |
| \checkmark | Ur |

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|---|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |