

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/SKR-271

1 Nome	SECTION I : IDENTIFICATION		
1. Name			
Present Past Other Name (if any):	: Churi wala balaji ka Temple :		
2. Location			
LONGITUDE 75 <sup>0</sup> 15 <sup>'</sup> E	LATITUDE 27 <sup>0</sup> 36 <sup>'</sup> N		
Address	Churi Bala ji ka Temple, Ward No. 25,		
	: Village (village code) Post : Laxmangarh District: Sikar State : Rajasthan PIN: 332311		
Approach	<ul> <li>The temple is situated 500 m from Railway Station and is 22 k.m. from Sikar &amp; 20 Km from Fatehpur bus stand.</li> </ul>		

#### 3. Property Type

 Buildings		Religious structures	_	Other Structures
Palace	$\checkmark$	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
Railway station		Monastery		
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings				
Residential building				
 0				
Engineering structure	-	en space and related ructures		<b>e:</b> It is simple structure raised a platform with portico followed
5	-	-	on	•
Engineering structure	-	ructures	on by nicł	a platform with portico followed room is the sancturm with a ne with the idol installed in it.
Engineering structure Bridge	-	ructures Public square	on by nicł The	a platform with portico followed room is the sancturm with a ne with the idol installed in it. a façade of the temple has
Engineering structure Bridge Tunnel	-	<b>ructures</b> Public square Park or garden	on by nich The pos	a platform with portico followed room is the sancturm with a ne with the idol installed in it. a façade of the temple has tter paintings of 'Ganeshji',
Engineering structure Bridge Tunnel	-	Public square Park or garden Graveyard	on by nicł The pos 'Ha	a platform with portico followed room is the sancturm with a ne with the idol installed in it. a façade of the temple has ther paintings of 'Ganeshji', numanji' & 'Krishna'. The
Engineering structure Bridge Tunnel	-	Public square Park or garden Graveyard Baolis, Well	on by nicł The pos 'Ha	a platform with portico followed room is the sancturm with a ne with the idol installed in it. a façade of the temple has tter paintings of 'Ganeshji',

		ABANDONED / IN USE : In use
Present	: R	eligious
Past	: R	eligious
5. Age (Source)		
PERIOD	:	
YEARS	: 1	9 <sup>th</sup> Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		

9. Physical Description and Decorative Features				
Context     Urban / Rural Setting     Surroundings			* Drawings (Attach extra sheet if necessary)	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)	
	Number of Blocks Number of Storys	:	01 01	
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The Temple is oriented East-West & faces the West.	
<u>AF</u>	CHITECTURAL STYLE			
•	Exteriors	:	The floors are stone claded in chess pattern & mess iced pillars.	
An	Interiors Movable Collections y <b>Other</b> (specify)	: : :		

## **SECTION II: DESCRIPTION**

#### **10. Construction Technology**

Structural System	:	Modern
<b>Building Techniques</b>	:	English bond
Material of Construction	:	Bricks, Cement, Stones etc.

#### **11. Condition Assessment**

In General

Good / Fair Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

#### In Brief (Attach extra sheet if necessary):

Well kept. Except some peeled off plaster frames the façade.

### 12. Threats to the Property

$\checkmark$	Na
$\checkmark$	Ne
$\checkmark$	Va
$\checkmark$	Ur

Natural Negligence Vandalism Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS