



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-274

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Hari Baxjee Passaria ki Haveli  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 36' N

#### Address

Near Chamari Bhawan, Ward No. 25, House-82,  
Lacchmangarh

: **Village (village code)**

**Post** : Laxmangarh

**District**: Sikar

**State** : Rajasthan

**PIN**: 332311

#### Approach

: The Haveli is situated 200 m from bus stand of lacchmangarh. It is 22 k.m. from Sikar & 20 Km from Fatehpur bus stand.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** Raised on a high plate form this building has in our mously lofty walls with small windows& ventilators. The facade & gateway is profusely painted with miniatures & floral patterns. Inside there is a small courtyard surrounded by porch. This façade is also adorned with paintings in shades of green, blue, red, yellow etc.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting**  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 02  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Haveli is oriented East-West & faces the West.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Massive paintings of royal procession  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, rubble masonry, lime plaster.

### 11. Condition Assessment

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration   |
| <input checked="" type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

A major chunk of painted plaster has fallen. Rest is fading. Soot, dirt & dust

## 12. Threats to the Property

---

- |   |                 |
|---|-----------------|
| ✓ | Natural         |
| ✓ | Negligence      |
| ✓ | Vandalism       |
| ✓ | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**