

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-385 **SECTION I: IDENTIFICATION** 1. Name Present Pali Ram Khemika Ki Haveli Past Other Name (if any): 2. Location 27⁰ 36' N LONGITUDE 75° 15' E LATITUDE **Address** Poddar Ka Mohalla, Ward No-8, Haveli No-204, Ramgarh Shekhawati Village (village code) Post: Ramgarh District: Sikar PIN: 331024 State: Rajasthan The Haveli is situated Churugate at Ramgarh Approach Shekhawati. It is 60 km from Sikar. And well connected by regular bus services from big cities. 3. Property Type Religious structures **Other Structures Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a building on a raised structures plinth with paintings on the wall. Cusped arched entrance, arcade. Bridge Public square high reliefs on the wall carved Tunnel Park or garden wooden door are noticed Other engineering structure Gravevard Baolis, Well Tank

Cave

| 4. Property Use | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-------------------------------|
| | | ABANDONED / IN USE: In use |
| Present Past | : | Residence Residence |
| 5. Age (Source) | | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition | : : : : : : : : : : : : : : : : : : : : | 19 th Century A.D. |
| 6. Ownership / Level of Protection | on | SINGLE /MULTIPLE : |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone | : : : : : : : : : : : : : : : : : : : : | Not protected |
| 7. AssociationWITH EVENTS | : | In History |
| In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) | : | Paliram Khemkajee |
| 8. Statement of Significance | | |
| Architectural Archaeological ✓ Historical Religious Any other (specify) | | |

SECTION II: DESCRIPTION

| 9. Physical Description and Decorative Features | | | | | | |
|-------------------------------------------------|---------------------------------------------------------------------|---------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) Urban | | | |
| | Garroundings | | Stand in Isolation Integral part of a Landscape / Street / Complex | | | |
| • | Quantification Area Dimension (L x B x H |) : | (m / cm/ feet / inch) | | | |
| | Number of Blocks Number of Storys | : | 02 02 | | | |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : : | The Haveli is oriented East - West & faces to the East L – patterned with a square courtyard | | | |
| <u>AR</u> | CCHITECTURAL STYLE Ornamentation Exteriors | : | Paintings on the wall, arcade resting on decorated pillars, high reliefs on the wall, decorated brackets, and carved wooden door are noticed. | | | |
| An | Interiors Movable Collections y Other (specify) | : | | | | |
| 10. | . Construction Technology | , | | | | |
| | Structural System | : | Brick-Masonry. Elements of Indo-Islamic elements are evident. | | | |
| | Building Techniques Material of Construction | : | Corbelling Brick, Cement mortar, wood, paints etc. | | | |
| 11. | . Condition Assessment | | | | | |
| | | Good Good | / Fair | | | |
| | Sign of Deterioration Serious Deterioration Danger of Disappearance | | | | | |
| In | Brief (Attach extra sheet if | neces | ssary): | | | |

Abrasion, flaking and discolourisation of paint layer, algal growth, etc are noticed.

| 12. Threats to the Property | | |
|-----------------------------|---|-----------------|
| | ✓ | Natural |
| | ✓ | Negligence |
| | | Vandalism |
| | | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|-------------------------------------------------------------|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |