

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-389 **SECTION I: IDENTIFICATION** 1. Name **Present** Unknown Haveli Past Other Name (if any): 2. Location 27⁰ 36' N LONGITUDE 75° 15' E LATITUDE **Address** Poddar Ka Mohalla, Ward No-8, Near- Churu gate Village (village code) Post: Ramgarh District: Sikar State: Rajasthan PIN: 331024 **Approach** The Haveli is situated Churugate at Ramgarh Shekhawati. It is 60 km from Sikar. And well connected by regular bus services from big cities. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a building in neglected structures condition. Remains of paintings on the wall, arches, arcade patterns, Public square Bridge Park or garden alcoves are noticed. Tunnel Graveyard Other engineering structure Baolis, Well Tank

Cave

4. Property Use		
		ABANDONED / IN USE: Abandoned
Present Past	:	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	18 th Century A.D.
6. Ownership / Level of Protecti	on	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify)	:	Not protected
Name Address Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : : :	In History
8. Statement of Significance		
Architectural Archaeological ✓ Historical Religious Any other (specify)		

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
	ougo		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	01 (m / cm/ feet / inch) 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Haveli is oriented East - West & faces to the West L – Patterned
<u>AR</u>	CHITECTURAL STYLE Ornamentation Exteriors		Wall painting, decorated brackets, carved wooden door,
An	Interiors Movable Collections y Other (specify)	: :	arcaded patterns are noticed.
10.	Construction Technology		
	Structural System	:	Stone Masonry. Elements of Indo-Islamic elements are evident.
	Building Techniques Material of Construction	:	Corbelling Stone, Cement mortar, wood, etc.
11.	Condition Assessment		
		Sood air	/ Fair
✓	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In I	Rrief (Attach extra sheet if I	nacas	seary).

It is in dilapidated condition. Losses of plaster, higher plants are noticed.

12. Threats to the Property	
→	Natural ✓ Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS