

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-403

SECTION I : IDENTIFICATION 1. Name Present Unknown haveli 2 Past : Other Name (if any): 2 2. Location 27⁰ 36['] N LONGITUDE 75⁰ 15['] E LATITUDE Address Ward No.9, Ramgarh Shekhawati Village (village code) : Post : Ramgarh District: Sikar Shekhawati State : Rajasthan PIN: 331024 The haveli is situated at Churchgate at Ramgarh Approach : Shekhawati. It is 60 km from Sikar and well connected by regular bus services from big cities. 3. Property Type **Religious structures Other Structures** Buildings Temple Palace Wall Fort Mosque Gateway Pillar Citadel Minar Church Others (specify) Govt. building Railway station Monastery Haveli Defence building Stupa Industrial building Tomb. Mausoleum Other public buildings \checkmark Residential building Engineering structure Open space and related Note: It is a L-shaped building on an elevated plinth. structures Decorated Bridge Public square brackets, arcade resting on Park or garden decorated pillars, carved wooden Tunnel door are noticed as decorative Other engineering structure Graveyard elements. Baolis, Well Tank Cave

		ABANDONED / IN USE : In use
Present	•	Residence
Past	÷	Residence
5. Age (Source)		
PERIOD	:	
YEARS	:	18 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	Not projected
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
✓ In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
✓ Historical		
Religious		

Any other (specify)

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Urban
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m. / am./ fact / in a
	Number of Blocks Number of Storys		(m / cm/ feet / inch 01 02
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The haveli is oriented East-West and faces the West Square
<u>AF</u> •	CHITECTURAL STYLE Ornamentation Exteriors	:	Intricately carved wooden door, cusped arched entrance arcade patterns are noticed.
An	Interiors Movable Collections y Other (specify)	: : :	It is on a raised platform
10	. Construction Technology		
	Structural System		Stone masonry, Indo-Islamic architectural elements an noticed
	Building Techniques Material of Construction	:	Corbelling Stone, cement, mortar wood etc.
11.	. Condition Assessment		
	In General G	/ hoo	′ Fair – good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Discolouration and fading of colour is evident. Not much deterioration is seen.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in some C in some of multiple shots months)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS