

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-405

<u>S</u> 1. Name	ECTION I : IDENTIFICATION		
Present Past Other Name (if any):	: Church Gate :		
2. Location			
LONGITUDE 75° 15' E LATITUDE 27° 36' N			
Address	ddress Ward No.10, Ramgarh Shekhawati		
Approach		arh District: Sikar PIN: 331024 Ited at Churchgate at Ramgarh km from Sikar and well connected	
3. Property Type			
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings ✓	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar ✓ Others (specify) Gate	
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a gate on the middle of the street. Not much decoration is noticed.	

		ABANDONED / IN USE : In use
Present	:	Gate
Past	:	Gate
5. Age (Source)		
PERIOD	:	
YEARS	:	18 th Century A.D.
Precise date of Construction	:	,
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	Not projected
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
✓ In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
 WITH PERSONS 		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
✓ Historical		
Religious		

Any other (specify)

I

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Urban
		Stand in Isolation Integral part of a Landscape / Street / Complex ✓
	n tification Dimension(L x B x H	,
	ber of Blocks ber of Storys	(m / cm/ feet / inch)
	ial Organization	: The Gate is oriented North-South and faces the South North
Plan Alloc	ation of Spaces	
	ECTURAL STYLE	
 Orna Exte 	imentation	: Decorated doors, arch pattern are noticed.
Inter		- Decorated doors, arch pattern are noticed.
	able Collections	
Any Oth	er (specify)	:
10. Con:	struction Technolog	/
Stru	ctural System	: Stone masonry
	ding Techniques	: Corbelling
Mate	erial of Construction	: Stone, lime mortar, metal
11. Con	dition Assessment	
In G	General	Good / Fair – Fair
-	n of Deterioration ious Deterioration	

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Loss of parts, cracks, etc are seen.

12. Threats to the Property

<	Nati
<	Neg
	Van
	Urba

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
13. Addio / Video	(related to rituals / performance / festivals etc.)
Reference	
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS