

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-407 **SECTION I: IDENTIFICATION** 1. Name Present Ganga Temple ka well Past Other Name (if any): 2. Location 27⁰ 36' N LONGITUDE 75° 15' E LATITUDE **Address** Near Churchgate, Ward No.9, Ramgarh Shekhawati Village (village code) Post Ramgarh District: Sikar Shekhawati **State**: Rajasthan PIN: 331024 The Temple is situated at Churchgate at Ramgarh Approach Shekhawati. It is 60 km from Sikar and well connected by regular bus services from big cities. 3. Property Type Religious structures **Other Structures Buildings** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a round shaped well with four octagonal minars with structures chajja drum, dome, cavorted lotus Bridge Public square Park or garden and pinnacle. Tunnel Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use			
		ABANDONED / IN USE :	Abandoned
Present			
Past Past	•		
rası	•		
5. Age (Source)			_
PERIOD	•		
YEARS	:	19 th Century A.D.	
Precise date of Construction	:	•	
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6. Ownership / Level of Protection	on		
,		SINGLE /MULTIPLE :	
Public: Archaeological Survey of	:	Not projected	
India / State Archaeology			
Department / Any Other (Please			
specify)			
Private	:		
Any other (Please specify)	:		
Name	:		
Address Phone	:		
FIIONE	•		
7. Association			
WITH EVENTS			
✓ In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:		
 WITH PERSONS 			
Patron	:		
Architect / Engineer	:		
Any other (specify)	:		
0.01-1111			
8. Statement of Significance			
Architectural			
Archaeological			
✓ Historical			
Religious Any other (specify)			
Arry other (specify)			

SECTION II: DESCRIPTION

9.	Physical Description and De	ecora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	(, e,e.,
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The well is oriented East-West and faces the East. Round
<u>AF</u>	Ornamentation Exteriors Interiors Movable Collections	:	Four octagonal minars with chajja, drum, dome, inverted lotus and pinnacle are noticed.
	y Other (specify)	:	It is on a raised platform.
10	. Construction Technology		
11	Structural System Building Techniques Material of Construction Condition Assessment	: : :	Stone masonry Corbelling Stone, lime, mortar.
	In General G	ood	/ Fair – good
	Sign of Deterioration Serious Deterioration Danger of Disappearance Brief (Attach extra sheet if r		
	ss of parts, algal growth are n		••
LU	oo or pario, argar growiii ale II	Juce	u.

12. Threats to the Property	
✓ ✓	Natural Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS