



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-417

SECTION I : IDENTIFICATION

1. Name

Present : Keshar Dev Poddar ki Bagichi
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 36' N

Address

Out of Church Gate, near the Art Palace, Ward No.25,
Ramgarh Shekhawati

: **Village (village code)**

Post : Ramgarh

District: Sikar

State : Rajasthan

PIN: 331024

Approach

: The bagichi is situated at Churchgate at Ramgarh Shekhawati. It is 60 km from Sikar and well connected by regular bus services from big cities.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)
Bagichi

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a small flower garden with a boundary wall around it.

4. Property Use

ABANDONED / IN USE : In use

Present : Garden
Past :

5. Age (Source)

PERIOD :
YEARS : 19th Century A.D.
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : Not projected
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - ✓ **In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - ✓ **Patron** : Keshavdev Poddarjee
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input checked="" type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting : Urban
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 02
Number of Storys : 01

- **Spatial Organization**
Orientation : The Bagichi is oriented East-West and faces the West
Plan : Rectangular
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Some flower plants are noticed.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Brick-masonry,
- Building Techniques** : Corbelling
- Material of Construction** : Brick, cement, mortar, etc.

11. Condition Assessment

In General **Good / Fair – good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Need proper care and maintenance.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS