

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-421 **SECTION I: IDENTIFICATION** 1. Name Present Mishra ka well **Past** Other Name (if any): 2. Location 27⁰ 36' N LONGITUDE 75° 15' E LATITUDE **Address** Out of Church Gate, Ward No.24, Near the Art Palace Village (village code) Post: Ramgarh District: Sikar State: Rajasthan PIN: 331024 Approach The well is situated at Churchgate at Ramgarh Shekhawati. It is 60 km from Sikar and well connected by regular bus services from big cities. 3. Property Type **Buildings** Religious structures **Other Structures** Wall Palace Temple Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a round shape well structures with four minars of octagonal shape with chajja drum, dome, Bridge Public square inverted lotus and pinnacle. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned.
Present Past	: Drinking water
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 20 th Century A.D. :
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	Not projected:::::::
7. Association	
 WITH EVENTS In History ✓ In Rituals In Building Construction Any other (specify) WITH PERSONS ✓ Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : :
8. Statement of Significance	
Architectural Archaeological ✓ Historical Religious Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and De	ecorative Features	
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban	
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex	
Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: (m / cm/ feet / inch) :	
 Spatial Organization Orientation Plan Allocation of Spaces 	The well is oriented East-West and faces the EastRound:	
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify) 10. Construction Technology	 Four octagonal minars with chajja, drum, dome, inverted lotus and pinnacle is noticed. It is on a raised platform 	
Structural System Building Techniques Material of Construction 11. Condition Assessment	: Brick-masonry,: Brick, cement, mortar etc.	
	ood / Fair – good	
Sign of Deterioration Serious Deterioration Danger of Disappearance In Brief (Attach extra sheet if n	necessary):	
Loss of parts, and negligence are prominent.		

12. Threats to the Property	
✓ ✓	Natural Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS