

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-467

SECTION I: IDENTIFICATION

1. Name	
Present Past Other Name (if any):	 Laxmi Nath jee ka temple Pandit Shri K.L. Shastri Tower
2. Location	
LONGITUDE 75° 15' E	LATITUDE 27 ⁰ 36 ['] N
Address	Ward No.15 , Ramgarh Shekawati
	: Village (village code) Post : Ramgarh District: Sikar State : Rajasthan PIN: 331024
Approach	: The temple is situated 48 km from Sikar Bus Stand and well connected by regular bus and train services from big cities.

3. Property Type

 Buildings		Religious structures		Other Structures
Palace	✓	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
Railway station		Monastery		
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings				
Residential building				
Engineering structure	-	en space and related		te: It is a single storied temple.
	-	uctures	The	e entrance has a projecting
Engineering structure Bridge Tunnel	-	•	The folia	a .
Bridge	-	<i>uctures</i> Public square	The folia are	e entrance has a projecting ated arch and porch. There
Bridge Tunnel	-	<i>uctures</i> Public square Park or garden	The folia are eith run	e entrance has a projecting ated arch and porch. There 2 foliated arch alcoves on her side. A cornice and railing is on top of the building. There
Bridge Tunnel	-	<i>uctures</i> Public square Park or garden Graveyard	The folia are eith run is ו	e entrance has a projecting ated arch and porch. There 2 foliated arch alcoves on her side. A cornice and railing is on top of the building. There mural work on the walls. The
Bridge Tunnel	-	<i>uctures</i> Public square Park or garden Graveyard Baolis, Well	The folia are eith run is r inte	e entrance has a projecting ated arch and porch. There 2 foliated arch alcoves on her side. A cornice and railing is on top of the building. There mural work on the walls. The erior is a pillared hall (open)
Bridge Tunnel	-	<i>uctures</i> Public square Park or garden Graveyard Baolis, Well Tank	The folia are eith run is r inte alse	e entrance has a projecting ated arch and porch. There 2 foliated arch alcoves on her side. A cornice and railing is on top of the building. There mural work on the walls. The erior is a pillared hall (open) o with painting decorations.
Bridge Tunnel	-	<i>uctures</i> Public square Park or garden Graveyard Baolis, Well Tank	The folia are eith run is r inte als The	e entrance has a projecting ated arch and porch. There 2 foliated arch alcoves on her side. A cornice and railing is on top of the building. There mural work on the walls. The erior is a pillared hall (open)

4. Property Use	
	ABANDONED / IN USE : In use
Present	: Religious
Past	: Religious
5. Age (Source)	
PERIOD	:
YEARS	: 18 th Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	1
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	
Any other (specify)	
8. Statement of Significance	
Architectural	The paintings are essentially decorative. The color scheme i
	mostly red ochre
Archaeological	
Historical	
Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and De	ecorative Features		
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban		
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex		
• Quantification Area Dimension (L x B x H)	: (m / m / for t / in al.)		
Number of Blocks Number of Storys	(m / cm/ feet / inch) : 02 : 02		
• Spatial Organization Orientation Plan Allocation of Spaces	The Temple is oriented North-South and faces the North		
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	 Foliated arches, cornice, mural work Foliated arch pillared hall 		
10. Construction Technology			
Structural System Building Techniques Material of Construction	 Indo-Persian Arcuate Brick, plaster 		
11. Condition Assessment			
In General G	ood / Fair – good		
Sign of Deterioration Serious Deterioration			

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling paint, discoloration, blackening.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in some C in some of multiple shots months)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS