


Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SKR-470

SECTION I: IDENTIFICATION

1. Name	
Present Past Other Name (if any):	 Ruia Bal Vatika School Khetridas jee ruia bal vatika
2. Location	
LONGITUDE 75 ⁰ 15 [°] E	LATITUDE 27 ⁰ 36 ['] N
Address	Ward No.15, Ramgarh Shekhawati out of the Bissna Gate
	: Village (village code) Post : Ramgarh District: Sikar State : Rajasthan PIN: 331024
Approach	: The school is situated 500 m from Ramgarh. It is 45 km from Sikar bus stand and well connected by regular bus and train services from big cities.

3. Property Type



4. Property Use

	ABANDONED / IN USE : In use
Present Past	: School :
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	20 th Century A.D.
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify)	
Name	:
Address Phone	
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS	
8. Statement of Significance	
✓ Architectural	The building now serves as a school. The mural work on the exterior is mostly decorative. The predominant colors are blue & red
Archaeological	

.

Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
Quantification Area Dimension (L x B x H Number of Blocks Number of Storys	H) : (m / cm/ feet / inch) : 01	
Spatial Organization Orientation Plan Allocation of Spaces	The school is oriented North-South and faces the South	
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify) 10. Construction Technology		
Structural System Building Techniques Material of Construction 11. Condition Assessment		
In General	Good / Fair – good	
Sign of Deterioration Serious Deterioration Danger of Disappearance	e	

In Brief (Attach extra sheet if necessary):

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in some C in some of multiple shots months)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS